SANTA RE SALO ARE	NO. OF COPIES RECEIVED		Form C-103
Signature 14-55 U.S. 10.5 Signature 14-55 Societable Proc	DISTRIBUTION	4	Supersedes Old C-102 and C-103
So, Indicent Type of Leane State Sta		NEW MEXICO OIL CONSERVATION COMMISSION	
Departure Sund Su		-	Eq. Indiana Thursday
SUNDRY NOTICES AND REPORTS ON WELLS OF NOTICES AND REPORTS ON WELLS I Same of Operation Silver Monument Minerals, Inc. 1. Address of Operation Silver Monument Minerals, Inc. 1. Address of Operation South 1980 Trucker 1. Address of Operation Box 1476, Lovington, New Mexico 88260 1. Address of Operation Tourner K 1880 Trucker 1. Address of Operation The North Complete K 1880 Trucker 1. Address of Operation The North Complete Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: Trucker 1. Address of Operation of Operations (Closerly state all pertinent densits, and give pertinent dates, including estimated date of starting any proposes work) see Full E 105. Pull Tubing, Rods and Pump, Remove well head, all fittings, valves and connections and pull approximately 2500' of 5½" casing, and plug as follows: CIBP topped with 5 sx cement at 3500' 25 sx cement on top of stub at 2500' 28 sx top of salt 1780' to 1880' 29 sx cement on of surface 360' 10 sx surface with marker 9.5 mud between plugs Trucker Sliver World R. Trucker 10. First Scarles Trucker 10.		-	
SUNDRY NOTICES AND REPORTS ON WELLS TO NOT THE THIS COUNTY OF THE THIS PROMISE TO THE THIS PROMISE THE THIS			
Attended Completed Complet		J	5. State On & Gas Ladse No.
Attended Completed Complet	(DO NOT USE THIS FORM FOR PR	RY NOTICES AND REPORTS ON WELLS OPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.	
3. Name of Concepts 3. Address of Coperator 4. Location of Moi 4. Location 4. Location of Moi 4. Location	OIL TO GAS	FORM C-101/ FOR SUCH PROPOSALS.)	
Silver Monument Minerals, Inc. Tucker 3. Address of Operator Box 1476, Lovington, New Mexico 88260 3. 4. Location of Well Unit Letter K 1880 Feet FROM THE South Line and 1980 Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: Subsequent Report of: Felds and Abandon X 1000 Feld and Abandon X 1000 Feld and Abandon X 1000 Committee Teampoon of the Data NOTICE OF INTENTION TO: Committee Teampoon of Committee Committee Committee Shall and Committee Shall be an	***************************************	OTHER-	
Box 1476, Lovington, New Mexico 88260 4. Location of Weil UNIT LETTER K 1880 FEET FROM THE SOUTH THE West LINE, SECTION 24 TOWNSHIP 7 S NAME 32 E NOTICE OF INTENTION TO: PERFORM MEMBLAIL MORK STORM STATE ANABOM PULL OR ALTER CASING THE MORALITY ARABOM PULL OR ALTER CASING TOWNSHIP FOR THE STORM SECTION SHOW whether DF, RT, GR, etc.) ALTERING CASING THE MORALITY ARABOM PULL OR ALTER CASING TOWNSOLATITY ARABOM PULL OR ALTER CASING TOWNSOLATITY ARABOM PULL TUDIng, Rods and Pump, Remove well head, all fittings, valves and connections and pull approximately 2500' of 5½" casing, and plug as follows: CIBP topped with 5 sx cement at 3500' 25 sx cement on top of stub at 2500' 28 sx top of salt 1780' to 1880' 28 sx top of salt 1780' to 1880' 28 sx top of salt 1780' to 1880' 10 ax surface with marker 9.5 mud between plugs 10. Field and Pool, or Wildpet 10. Field and Pool, or Wildpet 12. County 12	Silver Monument Mine	erals, Inc.	
4. Location of Well West Line, Section 24 Township 7 S AAMSE 32 E TROM THE South 15. Elevation (Show whether DF, RT, GR, etc.) Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK SUBSEQUENT REPORT OF: TEMPORALITY ABANDON ALTER CASING THANGARILY ABANDON CANTER CASING PULL OR ALTER CASING CANCE PLANS CASING TEST AND CEMENT AND EXEMENT AND ABANDON WENT TOWNS, SEE RULE 103. Pull Tubing, Rods and Pump, Remove well head, all fittings, valves and connections and pull approximately 2500' of 5½" casing, and plug as follows: CIBP topped with 5 sx cement at 3500' 25 sx cement on top of stub at 2500' 28 sx bottom of surface 360' 10 sx surface with Marker 9.5 mud between plugs 10. Line And CANTER CASING TITLE President OATE 3/26/74	•	New Mexico 88260	
THE West LINE, SECTION 24 TOWNSHIP 7 S SANGE 32 E NAME. 15. Elevation (Show whether DF, RT, GR, etc.) 12. County 16.	4. Location of Well		
15. Elevation (Show whether DP, RT, GR, etc.) 12. County 4449' GR Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PLUS AND ABANDON TEMPORALLY ABANDON PULI ON ALTER CASING OTHER OTHER OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose, work) SEE RULE 1103. Pull Tubing, Rods and Pump, Remove well head, all fittings, valves and connections and pull approximately 2500' of 5½" casing, and plug as follows: CIBP topped with 5 sx cement at 2500' 25 sx cement on top of stub at 2500' 28 sx top of salt 1780' to 1880' 28 sx top of salt 1780' to 1880' 10 sx surface with marker 9.5 mud between plugs B. I hereby certify that the information above is true and complete to the best of my knowledge and belief. Title President ONTICE OF REPORT OF CHARLES (12, County) Roosevelt Roosevelt Roosevelt Round Remote Of Notice, Report or Other Data SUBSEQUENT REPORT OF: SUBSEQUENT REPORT OF: SUBSEQUENT REPORT OF: CASING TEST AND CEMENT Jags PLUG AND ABANDONMENT CASING TEST AND CEMENT Jags ALTERING CASING CASING TEST AND CEMENT Jags PLUG AND ABANDONMENT CASING TEST AND CEMENT Jags ALTERING CASING CASING TEST AND CEMENT Jags ALTERING CASING CASING TEST AND CEMENT Jags ALTERING CASING CASING TEST AND CEMENT Jags CASING TEST AND	UNIT LETTER,	FEET FROM THE LINE AND FEET	FROM
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK TEMPORABICY ABANDON PULL ON ALTER CASING OTHER 17. Describe Proposed or Completed Operations (Clearly state all persinent details, and give persinent dates, including estimated date of starting any proposed work) HER WILE 103. Pull Tubing, Rods and Pump, Remove well head, all fittings, valves and connections and pull approximately 2500' of 5½" casing, and plug as follows: CIBP topped with 5 sx cement at 3500' 25 sx cement on top of stub at 2500' 28 sx top of salt 1780' to 1880' 28 sx bottom of surface 360' 10 sx surface with marker 9.5 mud between plugs IR. I hereby certify that the information above is true and complete to the best of my knowledge and belief. Title President ONTE 3/26/74	THE West LINE, SECTI	ON 24 TOWNSHIP 7 S RANGE 32 E	NMPM. (((()))
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK TEMPORABLY ABANDON THEN OTHER OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposes and pull approximately 2500' of 5½" casing, and plug as follows: CIBP topped with 5 sx cement at 3500' 25 sx cement on top of stub at 2500' 28 sx top of salt 1780' to 1880' 28 sx bottom of surface 360' 10 sx surface with marker 9.5 mud between plugs 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. President ONTICE PLUG AND ABANDON MARK ALTERING CASING PLUG AND ABANDON MARK ALTERING C		15. Elevation (Show whether DF, RT, GR, etc.)	12, County
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK TEMPORABLY ABANDON PULL OR ALTER CASING CHANGE PLANS CHANGE PLA		4449' GR	Roosevelt
PERFORM REMEDIAL WORK PLUG AND ABANDON			r Other Data
TEMPOBABILY ABANDON PULL OR ALTER CASING OTHER OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703. Pull Tubing, Rods and Pump, Remove well head, all fittings, valves and connections and pull approximately 2500' of 5½" casing, and plug as follows: CIBP topped with 5 sx cement at 3500' 25 sx cement on top of stub at 2500' 28 sx top of salt 1780' to 1880' 28 sx bottom of surface 360' 10 sx surface with marker 9.5 mud between plugs 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	NOTICE OF IN	NTENTION TO: SUBSEQ	JENT REPORT OF:
TEMPOBABILY ABANDON PULL OR ALTER CASING OTHER OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703. Pull Tubing, Rods and Pump, Remove well head, all fittings, valves and connections and pull approximately 2500' of 5½" casing, and plug as follows: CIBP topped with 5 sx cement at 3500' 25 sx cement on top of stub at 2500' 28 sx top of salt 1780' to 1880' 28 sx bottom of surface 360' 10 sx surface with marker 9.5 mud between plugs 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	PERFORM REMEDIAL WORK	THE AND ADDRESS TO	7
OTHER OT	i i i i i i i i i i i i i i i i i i i		ī -
17. Describe Proposed or Completed Operations (Clearly state all persinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Pull Tubing, Rods and Pump, Remove well head, all fittings, valves and connections and pull approximately 2500' of 5½" casing, and plug as follows: CIBP topped with 5 sx cement at 3500' 25 sx cement on top of stub at 2500' 28 sx top of salt 1780' to 1880' 28 sx bottom of surface 360' 10 sx surface with marker 9.5 mud between plugs 8.1 hereby certify that the information above is true and complete to the best of my knowledge and belief.		<u> </u>	PLUG AND ABANDONMENT
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Pull Tubing, Rods and Pump, Remove well head, all fittings, valves and connections and pull approximately 2500' of 5½" casing, and plug as follows: CIBP topped with 5 sx cement at 3500' 25 sx cement on top of stub at 2500' 28 sx top of salt 1780' to 1880' 28 sx bottom of surface 360' 10 sx surface with marker 9.5 mud between plugs 8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.			٠,
Pull Tubing, Rods and Pump, Remove well head, all fittings, valves and connections and pull approximately 2500' of 5½" casing, and plug as follows: CIBP topped with 5 sx cement at 3500' 25 sx cement on top of stub at 2500' 28 sx top of salt 1780' to 1880' 28 sx bottom of surface 360' 10 sx surface with marker 9.5 mud between plugs	OTHER		
Pull Tubing, Rods and Pump, Remove well head, all fittings, valves and connections and pull approximately 2500' of 5½" casing, and plug as follows: CIBP topped with 5 sx cement at 3500' 25 sx cement on top of stub at 2500' 28 sx top of salt 1780' to 1880' 28 sx bottom of surface 360' 10 sx surface with marker 9.5 mud between plugs			
TITLE President DATE 3/26/74	and pull approximum CIBP topped 25 sx cement 28 sx top of 28 sx bottom 10 sx surface	with 5 sx cement at 3500' on top of stub at 2500' salt 1780' to 1880' of surface 360' se with marker	
Orlo. Clarol "	IS, I hereby certify that the information	•	DATE 3/26/74
		Orlo. Etanol o	