

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole		7. Unit Agreement Name
2. Name of Operator Inserch Exploration, Inc.		8. Farm or Lease Name Rader
3. Address of Operator P. O. Box 4815, Midland, Texas 79704		9. Well No. 2
4. Location of Well UNIT LETTER E, 1880 FEET FROM THE North LINE AND 560 FEET FROM T-4E West LINE, SECTION 32, TOWNSHIP 5S, RANGE 33E, NMPM.		10. Field and Pool, or Wildcat S. Peterson (Fusselman)
15. Elevation (Show whether DF, RT, GR, etc.) 4384.5 GR		12. County Roosevelt

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plans are to plug and abandon well within 30 days as follows:

Set CIBP at 7827 w/35 Class H cement from 7792' to 7827'.
Cut off 5-1/2" casing at 6890'.
Lay 25 sack Class H cement plug from 6750' to 6850'.
Lay 40 sack Class H cement plug from 1936' to 2036'.
Lay 10 sack Class H cement plug at surface.
Cut off 9-5/8" casinghead.
Weld steel plate to 9-5/8" casing.
Install dry hole marker.

180' plug at 3500'

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED H. F. Burnett H. F. Burnett TITLE Production Superintendent DATE 7/19/82

ORIGINAL SIGNED BY JERRY SEXTON APPROVED BY JERRY SEXTON TITLE DISTRICT SUPR. DATE SEP 27 1982