

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>

5. State Oil & Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole		7. Unit Agreement Name
2. Name of Operator Enserch Exploration, Inc.		8. Farm or Lease Name Lambirth
3. Address of Operator P. O. Box 4815, Midland, Texas 79704		9. Well No. 11
4. Location of Well UNIT LETTER M, 660 FEET FROM THE North LINE AND 660 FEET FROM THE West LINE, SECTION 1 TOWNSHIP 16 RANGE 33 NMPM.		10. Field and Pool, or Wildcat Undesignated
15. Elevation (Show whether DF, RT, GR, etc.) 4424.9 GR		12. County Roosevelt

## Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

### SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plans are to plug and abandon well within 30 days as follows:

Set CIBP at 3890' with 35' Class H cement from 3855' to 3890'.  
Cut off 5-1/2" casing at 3420'.  
Lay 25 sack Class H cement plug from 3370' to 3470'.  
Lay 40 sack Class H cement plug from 1947' to 2047'.  
Lay 10 sack Class H cement plug at surface.  
Cut off 9-5/8" casinghead.  
Weld steel plate on 9-5/8" casing.  
Install dry hole marker.

100' PLUG @ 1625'

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED H.F. Burnett H.F. Burnett TITLE Production Superintendent DATE 7/19/82

ORIGINAL SIGNED BY

JERRY SEXTON

DISTRICT AN SUPR.

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL \_\_\_\_\_

AUG 2 - 1982