

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

API #30-041-20614

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER- ☐	7. Unit Agreement Name ---
2. Name of Operator <u>Phillips Off Company</u>	8. Farm or Lease Name <u>Wortham-A</u>
3. Address of Operator <u>Room 401, 4001 Penbrook, Odessa, Texas 79762</u>	9. Well No. <u>1</u>
4. Location of Well UNIT LETTER <u>L</u> <u>2304</u> FEET FROM THE <u>south</u> LINE AND <u>660</u> FEET FROM THE <u>west</u> LINE, SECTION <u>8</u> TOWNSHIP <u>6-S</u> RANGE <u>36-E</u> NMPM.	10. Field and Pool, or Wildcat <u>Undesignated</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>4184 DF, 4185' KB</u>	12. County <u>Roosevelt</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐
PULL OR ALTER CASING ☐	OTHER <u>Confirm verbal P & A approval</u> ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐	ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

(Perforations open 4192-4220' and 4228-4248')

P & A as follows:

- COOH w/tbg and pkr.
- RIH w/EZ drill, sqze ret on 2-3/8" tbg. Set ret at 4100'.
- Sqze perfs 4192-4248' w/75 sks C1 "C", 14.8#/gal, 1.32 cu ft/sk neat cmt. Pull out of ret and reverse tbg clean.
- Displace hole w/9.5#/gal mud laden fluid.
- POOH to 3425' and spot 35 sks C1 "C", 14.8#/gal, 1.32 cu ft/sk neat cmt. Pull 15 jts and rev tbg clean. COOH.
- Jameson and Cafey to freepoint, cut and pull 5-1/2" OD csg. Est TOC at 740'.
- GIH w/tbg to 50' below cutoff point and spot 50 sks C1 "C" w/2% CaCl, 14.8#/gal, 1.32 cu ft/sk cmt. Pull 8 jts and rev tbg clean.
- POOH at 400' and spot 110 sks C1 "C", 14.8#/gal, 1.32 cu ft/sk neat cmt. TOC surface. COOH w/tbg.
- Cutoff CHF, weld on 1/2" plate, instl permanent marker. Fill in hole and clean up location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. J. Mueller TITLE Sr. Engr. Specialist DATE 1-6-82

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

mcf