

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
N. M. OIL CONS. COMMISSION
PRO. BOX 1980
HOBBS, NEW MEXICO 88240

Budget Bureau No. 1004-1-1
Expires August 31, 1985
5. LEASE DESIGNATION AND SERIAL NO.

NM-37611
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT--" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. NAME OF OPERATOR
EP Operating Company
3. ADDRESS OF OPERATOR
6 Desta Dr., Suite 5250, Midland, TX 79705-5510
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
660' FNL & 660' FEL (NE $\frac{1}{4}$ NE $\frac{1}{4}$) Section 20, T4S, R33E
14. PERMIT NO.
15. ELEVATIONS (Show whether DF, RT, GR, etc.)
4377.8' GR

7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Scott Federal
9. WELL NO.
1
10. FIELD AND POOL, OR WILDCAT
North Peterson Penn
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 20, T4S, R33E
12. COUNTY OR PARISH
Roosevelt
13. STATE
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☒
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐
REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Plan to dump 35' cement on top of existing CIBP @ 6830'. Set 5 $\frac{1}{2}$ " CIBP @ 6775' with 35' cement on top. Circulate hole with mud laden fluid. Cut casing @ \pm 3100'. Spot 35 sack plug in casing stub. Tag plug. Spot 35 sack plug at 3100'. Spot 35 sack plug at 2043'. Spot 35 sack plug at 400'. Cut off wellhead. Spot 10 sack surface plug. Install dry hole marker.

18. I hereby certify that the foregoing is true and correct

SIGNED S. D. Reed
S. D. Reed

TITLE Production Superintendent

DATE April 14, 1988

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED
PETER W. CHESTER

APR 18 1988

BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA

*See Instructions on Reverse Side

RECORDED
APR 21 1968
OCD
HOBB'S OFFICE