

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Geology, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2083
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-041-20666
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name TAYLOR
8. Well No. #1 SWD
9. Pool name or Wildcat Undesignated Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER SWD	
2. Name of Operator Bledsoe Partners, Inc.	
3. Address of Operator 3908 North Peniel, Bethany Bank Tower, Bethany, OK 73008	
4. Well Location Unit Letter C : 660 Feet From The North Line and 1980 Feet From The West Line Section 11 Township 6S Range 33E NMPM Roosevelt County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4408 GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pump 100' plug @ 3559 - (50' in and out of 8 5/8). **T A G**
2. Load hole with mud.
3. Spot 100' cement plug @ 400'.
4. Spot plug 30' to surface.
5. Cut & cap surface csg., weld on dry hole marker, clean location.

THIS NOTICE MUST BE NOTED 24
HOURS BEFORE THE BEGINNING OF
ANY OPERATIONS FOR THE OILS

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Eva Wheat

Agent

DATE 3-22-94

TYPE OR PRINT NAME **Eva Wheat**

TELEPHONE NO. 817-629-8563

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

MAR 25 1994

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAR 24 1994

**OCU RECORDS
OFFICE**