- STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

40. 97 COPIES SCCEIVED	7	
DISTRUBUTION	1	Ì
SANTA FE		Γ
rile		
U.S.G.S.		Ī
LAND OFFICE		
DPERATOR		;

OIL CONSERVATION DIVISION P. O. BOX 2088

Form C-103

SANTA FE	<u> </u>	SANTA FE, NEW MEXICO 87501			Revised 10-1-	
FILE	 			[G	i. Indicate Type of	· · · · · · · · · · · · · · · · · · ·
U.S.O.S.						L
DERATOR	 	*		<u> </u>	State	Fon X
DE EN PION				5.	State Oil & Gus L	,easn No.
	- <u></u>				***	
(DO NOT USE THIS FOR	SUNDRY NOTICES A	ND REPORTS ON	NELLS BACK TO A DIFFERENT RESERVOIR CH PROPOSALS.)	. (
OIL GAS WELL	OTHER:	P&A		7.	Unit Agreement No	ame
2. Name of Operator		Tun			Farm or Lease Na	
Yates Petro	leum Corporation	·			Howard XY	me
J. Address of Operator	•			9.	Well No.	
105 South 41	th St., Artesia,	NM 88210			1-Y	
1. Location of Well				10	. Field and Pool, a	or Wildcat
UNIT LETTER M 510 FEET FROM THE South LINE AND 990					omahawk SA	
17	17					THITTI
THE West	NE, SECTION	TOWNSHIP7S	32E	MMSM.		
 						///////////////////////////////////////
15. Elevation (Show whether DF, RT, GR, etc.)			12	. County	177777	
4470.2' GR				Ro	osevelt	
16.	Theck Appropriate B	ox To Indicate 8	Nature of Notice, Repor	e os Oshaa	<u></u>	<i>· · · · · · · · · · · · · · · · · · · </i>
NOTICE	E OF INTENTION TO					
		•	30831	EQUENT RI	EPORT OF:	
PERFORM REMEDIAL WORK	P	LUG AND ABANDON	REMEDIAL WORK	\Box	_	
TEMPORARILY ABANDON			COMMENCE DRILLING OPHS.	H	ALTERING C	
PULL OR ALTER CASING		HANGE PLANS			PLUG AND A	BANDONMENT X
		manue Peans	BOL THEMES ONE TEST DRIESS	L.J.		
OTHER			OTHER			L
UIACA	·····	——————————————————————————————————————				
17. Describe Proposed or Comp work) SEE RULE 1703.	oleted Operations (Clearly	state all pertinent det	l ails, and give pertinent dates,	including esti	nated date of start	ing any proposed
·	£ - 1.1					
Plugged well as						
Spot 23 sx cemen	t plug with 3% C	aCl2 at 4100'	across perforation	ıs.		
Set CIBP at 3955						
Spot 25 sx cemen	t plug at 3444'.					
Cut 4-1/2" casin	g at 2800 ' and p					
Spot 35 sx cemen	t plug at 2850'.	Tag plug at	2614'.			
Spot 35 sx cemen	t plug at 1950'.					
Spot 35 sx cemen	t plug at 1735'.	Tag plug at	1561'.			
Spot 10 sx cemen	t surface plug.	.	-			
Install dry hole	marker.					
Plugging complete						
00 g ====p10e	5 51 67.					
•						

1 Day 6 W	OIT & CAS INSPECTOR	JAN 0 4 1989
oriones (and a forther	Production Supervisor	DATE 4-3-87
is. I hereby certify that the information above is true and comp	lete to the boat of my knowledge and belief.	