

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P&A	7. Unit Agreement Name
2. Name of Operator Yates Petroleum Corporation	8. Farm or Lease Name Howard XY
3. Address of Operator 105 South 4th St., Artesia, NM 88210	9. Well No. 1-Y
4. Location of Well UNIT LETTER <u>M</u> <u>510</u> FEET FROM THE <u>South</u> LINE AND <u>990</u> FEET FROM THE <u>West</u> LINE, SECTION <u>17</u> TOWNSHIP <u>7S</u> RANGE <u>32E</u> NMPM.	10. Field and Pool, or Wildcat Tomahawk SA
15. Elevation (Show whether DF, RT, GR, etc.) 4470.2' GR	12. County Roosevelt

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER _____ <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged well as follows:
Spot 25 sx cement plug with 3% CaCl2 at 4100' across perforations.
Set CIBP at 3955'.
Spot 25 sx cement plug at 3444'.
Cut 4-1/2" casing at 2800' and pulled.
Spot 35 sx cement plug at 2850'. Tag plug at 2614'.
Spot 35 sx cement plug at 1950'.
Spot 35 sx cement plug at 1735'. Tag plug at 1561'.
Spot 10 sx cement surface plug.
Install dry hole marker.
Plugging completed 3-31-87.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Production Supervisor DATE 4-3-87

APPROVED BY [Signature] TITLE OIL & GAS INSPECTOR DATE JAN 04 1989

CONDITIONS OF APPROVAL, IF ANY: