Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

P.O. Box 2088

DISTRICT II P.O. Drawer DD, Artesia, NM 88210 OIL CONSERVATION DIVISION

Santa Fe, New Mexico 87504-2088

WELL, API NO.	30-041	-20194
5. Indicate Type		

5.	Indicate Type of L	STATE XX	FEE
5.	State Oil & Gas L	ease No.	
	LG 1296		
7			

Diedbier in			STATE LXX FEE L				
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410					6. State Oil & Gas Lease No. LG 1296		
	SUNDRY NOTICES AND REPORTS ON WELLS						
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)					7. Lease Name or Unit Agreement Name		
1.	Type of Well: Oil. WELL XX	OAS WELL	OTHER		El Paso State		
2.	Name of Operator				8. Well No.		
	Bledsoe Petro	Corp			4		
3.	Address of Operator		9. Pool name or Wildcat				
	3908 N.Peniel, Suite 500, Bethany, OK 73008		South Peterson Penn/ Assoc				
4.	4. Well Location						
	Unit Letter H: 1980 Feet From The North Line and 510 Feet From The East Line						
,,	Section 8	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		nge 34E	NMPM Roosevelt County		
10. Elevation (Show whether DF, RKB, RT, C				DF, KKB, KI, GK, &C.)			
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data							
NOTICE OF INTENTION TO:			ENTION TO:	SUB	SEQUENT REPORT OF:		
PE	RFORM REMEDIAL WOR	к 🗌	PLUG AND ABANDON XX	REMEDIAL WORK	ALTERING CASING		
ΤE	MPORARILY ABANDON		CHANGE PLANS	COMMENCE DRILLING	GOPNS. PLUG AND ABANDONMENT		
PULL OR ALTER CASING CA				CASING TEST AND CI	EMENT JOB .		
от	OTHER:			OTHER:			
12	12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.						

- 1. Set CIBP at 7600', cap with 35' cement
- 2. Fill hole with plug mud (9.3#/gal)
- 3. Cut 4 1/2" at free point, estimated to be approx 5500', pull 4 1/2" csg
- 4. Spot 100 ft cement plug at cut off point, 1/2 in csg. 1/2 out of csg
- 5. Spot 100' cement plug at 3400'
- 6. Spot 100' plug at base of 8 5/8' surf casing, 1/2 in csg. 1/2 out of csg
- 7. Spot 30' cement plug at surface
- 8. Cut off surf casing & weld on metal plate, place steel I.D. marker per Para B-2 rule 202, New Mexico Q.C.D.

CARL MARKET

I hereby certify that the information above is true and complete to the best of my knowledge and belief. 12/20/91 _ TITLE ___ <u>Emgineer</u> _ DATE _ SIONATURE __S (405) 789-5053 TYPE OR PRINT NAME Tom Conrov (This space for State Use) _ DATE JAN 0 3 '92

- TITLE -

APPROVED BY -

CONDITIONS OF APPROVAL, IF ANY: