Submit 3 Copies To Appropriate District Office District [State of ergy, Minerals، د		Form C-10 Revised March 25, 19							
1625 N. French Dr., Hobbs, NM 88240				WELL API NO.						
District II 811 South First Artonic NIM 88210	OIL CONSERV	DIVISION	30-025-00368 5. Indicate Type of Lease							
District III	1 South First, Artesia, NM 88210 OIL CONSERVATION DIVISION strict III 1220 South St. Francis Dr.									
1000 Rio Brazos Rd., Aztec, NM 87410	000 Rio Brazos Rd., Aztec, NM 87410				I FEE □					
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87504	Santa F	 State Oil & Gas Lease No. B-9683 								
SUNDRY NOTIO	7. Lease Name or Unit Agreement Name:									
(DO NOT USE THIS FORM FOR PROPOS DIFFERENT RESERVOIR. USE "APPLIC										
PROPOSALS.)			N SOCH	Anderson Ranch Unit						
1. Type of Well:										
Oil Well Gas Well										
2. Name of Operator	8. Well No.									
Grand Banks Energy 3. Address of Operator	16									
10 Desta Drive, Ste 300E, N	9. Pool name or Wildcat									
4. Well Location	Wolfcamp									
Unit Letter: 1 - 1980 f	Unit Letter: T - 1980 feet from the South line and 660 feet from the West line									
Section: 2 Townshi			NMPM:	County: Le	a					
	10. Elevation (Show) 4331	whether DF ' DF	R, RKB, RT, GR, etc.	.)						
11. Check A	ppropriate Box to In	dicate Na	ature of Notice. I	Report or Other	Data					
NOTICE OF IN	SEQUENT REP									
PERFORM REMEDIAL WORK			REMEDIAL WORK	< ত্র						
	CHANGE PLANS		COMMENCE DRIL	LING OPNS. 🗌						
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AN CEMENT JOB		ABANDONMENT					
OTHER:			OTHER:							
10 D 1										

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Recent remedial work was performed on this well to locate and repair a tubular/packer leak in this disposal wellbore. The packer and several joints of tubing were replaced. As part of the operation the casing was successfully tested from the surface to 9695' to 500 psi for 30 minutes prior to running the new equipment. The new packer was set at 9677'. After the new packer and tubing was run the casing was again tested to 500 psi on March 8, 2001. Once again, the wellbore successfully held pressure for 30 minutes. The disposal well is currently taking water on a vacuum as it was prior to the workover operation.

The pressure chart is attached.

5

The new wellbore schematic is attached

Conditions of approval, if any:	$\{ j_{ij} \}_{i \in I}$	
APPPROVED BY	TITLE	÷ ⇔
(This space for State use)		
Type or print name Terry M. Duffey		Telephone No. (915) 686-9790
SIGNATURE: m Cufling	TITLE: Agent	DATE: Mar 19, 2001
I hereby certify that the information above is true a	and complete to the best of my knowle	edge and belief.

AFE# Lease		Well#	Description	Date Field		County St. 1				
				Duie		County	State	Activity Description	Daily\$	Cum\$
	Anderson Ranch Unit	16	Repair possible casing leak	06-Mar-01	Anderson Ranch	Lea	NM	Open well. No pressure. PU 5-1/2" nickel plated lock set packer, 1.81" profile nipple and on/off tool. GIH testing tubing. Found two bad joints. Some several ring seals bad also.	1,450	29,063
				07-Mar-01	1 Anderson Lea NM FIH testing tubing. Left packer Ranch Swinging at 8508'. Laid down 38 its of 3-1/2" and 6 its of 2-7/8" tubing that failed to test. Most failed due to excessive scale buildup. Others due to separated liners. Replaced ring seals on every connection.	2,600	31,663			
				08-Mar-01	Anderson Ranch	Lea		Open well. No pressure. Unloaded 37 jts of 3-1/2" Duoline tubing. FIH testing tubing. Set packer at 9677'. Released on/off tool. Circulated packer fluid. ND BOP. Re-latch on/off tool. NU WH. Tested casing and recorded on chart to 500 psi. OK. Hook up injection line and began disposing water into wellbore. Sent 38 jts 3-1/2" and 6 jts 2-7/8" Duoline tubing to Rice Engineering for inspection and repair. FINAL REPORT.	31,149	62,812





.