

MIDLAND E & P DIVISION

WELL WORK RECOMMENDATIONS

Proposals for Well Reconditioning and Subsurface Maintenance
Workovers, Expense DD's, PB's, and Conversions

Lease: NEW MEXICO "S" Well No. 1
Field: ARMERSON RANCH
County: LEA State: NEW MEXICO

RECOMMENDED PROCEDURE:

- I. P&P Procedure for the following work:
1. M.T.P. Pull Both Strings of Tubing 2" diameter
& 24" Deviation
 2. Pickout the OTIS and Pump Set @ 9800'
 3. Spot 100' cement Plug above Deviation
Perforations
 4. Set Plug in Model 10" P&P

- II. Run 2" Tubing of Return Line set @ 9800'
Spot & Test

Note: P&P Procedure Reviewed 11/12/73 10-2-73

(C) P&P Procedure Review for the possibility of going
Back to the 10000' zone

APP 12-2-73