

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN THE INDICATE\*  
(Other instructions on re-  
verse side)Form approved.  
Budget Bureau No. 42-R1424

5. LEASE DESIGNATION AND SERIAL NO.

NM 0569

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL ☐ GAS ☐  
WELL WELL OTHER

INJECTION WELL

RECEIVED

2. NAME OF OPERATOR

THE OIL &amp; GAS CO.

MAY 10 1975

3. ADDRESS OF OPERATOR

P. O. BOX 837, HOBBS, NEW MEXICO 88240 U. S. GEOLOGICAL SURVEY  
4. LOCATION OF WELL (Report location clearly and in accordance with any special requirements.  
See also space 17 below.)  
At surfaceUnit letter D, 660' from the north line and 1080' from the  
east line, section 31, township 15, range 32 NMPM.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, OR, etc.)

4149 CR

7. UNIT AGREEMENT NAME

ROBINSON UNIT

8. FARM OR LEASE NAME

Robinson Unit Tr. 2-31

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Malj. Grayb. S. A.

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

31-16S-32E

12. COUNTY OR PARISH

Lea

13. STATE

N. Mex.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-  
nent to this work.)\*

1. 4 1/2" BP set @ 3600'.

Dump 4 ex. cement on top.

2. Spot 25 ex. plug @ 2500'.

3. Spot 35 ex. plug @ 900'.

4. Spot 35 ex. plug @ 550', cut off 4 1/2".

5. Spot 50 ex. plug @ 250'.

6. Spot 10 ex. plug @ surface.

Install dry-hole marker and clean location

Load hole w/mud and displace all plugs w/mud.

7. Date abandoned - 4-24-75.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

AGENT

DATE

5/2/75

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side