Form 3160-5 (November 1983) (Formerly 9-331)

## UNITER TATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLIC.
(Other Instructions on reverse side)

Budget Bureau No. 1004-0135 Expires August 31, 1985

DOTAL TO OF LEWIS THE TOTAL THE TENTE OF THE	5. LEASE DESIGNATION AND SERIAL NO.
CUMPRY MOTIOFO AND DEPORTS ON WELLS	LC-059576
SUNDRY NOTICES AND REPORTS ON WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir  Use "APPLICATION FOR PERMIT - " for such proposals.)	r.
1.	7. UNIT AGREEMENT NAME
OIL GAS OTHER WIW	Maljamar Grayburg Unit
2. NAME OF OPERATOR	
The Wiser Oil Company	8. WELL NAME AND NO.
3. ADDRESS OF OPERATOR	10
P.O. Box 2568 Hobbs, New Mexico 88241	9. API WELL NO.
LOCATION OF WELL (Report location clearly and in accordance with any State requirements.)	30-025-00449 10. FIELD AND POOL, OR WILDCAT
See also space 17 below.)	Maljamar Grayburg San Andres
At surface 660' FSL & 660' FWL	11. SEC., T., R., M., OR BLK. AND
Unit M	SURVEY OR AREA
	Sec. 3-T17S-R32E
14. PERMIT NO 15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13 STATE
4168'	12. COUNTY OR PARISH 13. STATE Lea County NM
16. Check Appropriate Box to indicate Nature of Notice, Re	enort or Other Data
1	sport, or other but
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT OFF PULL OR ALTER CASING WATER SH	UT OFF DEPARTMENT
- I WANDARDA	UT-OFF REPAIRING WELL
FRACTURE TREAT MULTIPLE COMPLETE FRACTURE	TREATMENT ALTERING CASING
SHOOT OR ACIDIZE ABANDON* SHOOTING	OR ACIDIZING ABANDONMENT *
Silco into	OR ACIDIZING ABANDONMENT *
REPAIR WELL CHANGE PLANS (Other)	
(Note: Report results of multiple completion on Well  (Other) Temporary Abandon Completion or Recompletion Report and Log form	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS: (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any	
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)	
Wiser requests approval to Temporary Abandon the well by the procedure listed below.	
Perforations: 3920'-4144' 5-1/2" 14# casing set @ 4255' 8-5/8" casing set @ 366'	
1. POH w/5-1/2" perma latch pkr @ 3848'. TIH & set CIBP @ 3850'.	
2. Pressure test plug & csg. to 500#.	
3. If holds circulate pkr, fluid.	
4. POH w/tbg.	
5. Pressure test csg. to 500# with a pressure recorder.	
6. Shut well in.	
BLM @ 505.393.3612	, , ,
*Note: Call OCD before beginning work.	
•	
18. I hereby certify that the foregoing is true and correct.	
H .	
SIGNED TITLE Superintendent	DATE November 19, 2002
(This space for Federal or State office use)	
APPROVED B (ORIG. SGD.) JOE G. LAPAITLE CONDITIONS OF APPROVAL, IF ANY:	DATE ///0/03
GWW	′ /

\*See Instruction On Reverse Side

98 31 24 52 30 38

GEVICEA