State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I

OIL CONSERVATION DIVISION

sIndicate Type of Lease «State Oil & Gas Lease N	STATE	FEE
WELL API NO. 30-025-00524		

O Pa NIM O	7505	30-025-00524
Santa Fe, NM 8	7303	sIndicate Type of Lease
P.O. Drawer DD, Artesia, NM 88210		STATE FEE FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	₀State Oil & Gas Lease No. B 871	
SUNDRY NOTICES AND REPORTS ON WE	LLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN DIFFERENT RESERVOIR. USE "APPLICATION FOR PE	OR PLUG BACK TO A	₁Lease Name or Unit Agreement Name
(FORM C-101) FOR SUCH PROPOSALS.)		NEW MEXICO "O" STATE
Type of Well: OIL GAS WELL WELL OTHER		
2Name of Operator SOUTHWEST ROYALTIE, INC.		eWell No. 22
*Address of Operator		∍Pool name or Wildcat MALJAMAR
P. O. BOX 11390; MIDLAND, TX 79702		MICHEOCHRICAL
4Well Location Unit Letter F 1980 Feet From The NORTH	Line and1982	Feet From The WEST Line
12 Section 17S Township 32E	Range	NMPM LEA County
12 Section 10 Televation (Show whether Did 4330 GL		
Double Double Indicate N	lature of Notice. Ret	port, or Other Data
	SHR	SEQUENT REPORT OF:
NOTICE OF INTENTION TO:		ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON	i	
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING O	
PULL OR ALTER CASING	CASING TEST AND CEME	ENI JOB
	t .	_
OTHER:	OTHER:	
Describe Proposed or Completed Operations (Clearly state all pertinent details, and g		stimated date of starting any proposed
		stimated date of starting any proposed
12Describe Proposed or Completed Operations (Clearly state all pertinent details, and gwork) SEE RULE 1103.	ive pertinent dates, including es	
12Describe Proposed or Completed Operations (Clearly state all pertinent details, and gwork) SEE RULE 1103.	ive pertinent dates, including es	
12Describe Proposed or Completed Operations (Clearly state all pertinent details, and gwork) SEE RULE 1103. 1) MIRU PLUGGING CONTRACTOR. 2) SET CIBP @ 4100' +/-, & CAP W/ 35' OF CMT (TAG). LOAD CSG W/ N 3) SPO1 10 SXPLUG FROM 3400' - 3550'.	IUD.	WHICHEVER IS GREATER
12Describe Proposed or Completed Operations (Clearly state all pertinent details, and gwork) SEE RULE 1103. 1) MIRU PLUGGING CONTRACTOR. 2) SET CIBP @ 4100' +/-, & CAP W/ 35' OF CMT (TAG). LOAD CSG W/ M 3) SPOT 10 SX PLUG FROM 3400' - 3550'. ALL PLUGS A R2 4) PERF CSG @ 2400' & SQZ W/ 50 SX. LEAVING 10 SX INSIDE CSG - 1	IUD.	WHICHEVER IS GREATER
12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and gwork) SEE RULE 1103. 1) MIRU PLUGGING CONTRACTOR. 2) SET CIBP @ 4100' +/-, & CAP W/ 35' OF CMT (TAG). LOAD CSG W/ M 3) SPOT 10 SX PLUG FROM 3400' - 3550'. ALL PLUGS A RE 4) PERF CSG @ 2400' & SQZ W/ 50 SX. LEAVING 10 SX INSIDE CSG - 15 5) CUT 4 1/2" 9.5# CSG @ 1400' +/ TOH & LD CSG.	IUD.	WHICHEVER IS GREATER
12Describe Proposed or Completed Operations (Clearly state all pertinent details, and gwork) SEE RULE 1103. 1) MIRU PLUGGING CONTRACTOR. 2) SET CIBP @ 4100' +/-, & CAP W/ 35' OF CMT (TAG). LOAD CSG W/ M 3) SPOT 10 SX PLUG FROM 3400' - 3550'. ALL PLUGS ARE 4) PERF CSG @ 2400' & SQZ W/ 50 SX. LEAVING 10 SX INSIDE CSG - 15 5) CUT 4 1/2" 9.5# CSG @ 1400' +/ TOH & LD CSG. 6) SPOT 50X CMT PLUG FROM 1200' - 1400', TAG PLUG.	IUD.	WHICHEVER IS GREATER
12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and gwork) SEE RULE 1103. 1) MIRU PLUGGING CONTRACTOR. 2) SET CIBP @ 4100' +/-, & CAP W/ 35' OF CMT (TAG). LOAD CSG W/ M 3) SPOT 10 SX PLUG FROM 3400' - 3550'. ALL PLUGS A RESERVED A STATE OF CSG @ 2400' & SQZ W/ 50 SX. LEAVING 10 SX INSIDE CSG - 15 CUT 4 1/2" 9.5# CSG @ 1400' +/ TOH & LD CSG. 6) SPOT 50X CMT PLUG FROM 1200' - 1400', TAG PLUG. 7) SPOT 25 SX PLUG FROM 3' - 103'.	IUD. Z 5 SX OR 100° C	WHICHEVER IS GREATER OF 189 1011 12 13 TA 15 TO
12Describe Proposed or Completed Operations (Clearly state all pertinent details, and gwork) SEE RULE 1103. 1) MIRU PLUGGING CONTRACTOR. 2) SET CIBP @ 4100' +/-, & CAP W/ 35' OF CMT (TAG). LOAD CSG W/ M 3) SPOT 10 SX PLUG FROM 3400' - 3550'. ALL PLUGS ARE 4) PERF CSG @ 2400' & SQZ W/ 50 SX. LEAVING 10 SX INSIDE CSG - 15 5) CUT 4 1/2" 9.5# CSG @ 1400' +/ TOH & LD CSG. 6) SPOT 50X CMT PLUG FROM 1200' - 1400', TAG PLUG.	THE COMMUSSION	WHICHEVER IS GREATER WHICHEVER IS GREATER OF 189 1011 12 13 19 15 15 15 15 15 15 15 15 15 15 15 15 15
12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and gwork) SEE RULE 1103. 1) MIRU PLUGGING CONTRACTOR. 2) SET CIBP @ 4100' +/-, & CAP W/ 35' OF CMT (TAG). LOAD CSG W/ M 3) SPOT 10 SX PLUG FROM 3400' - 3550'. ALL PLUGS A RESERVED A STATE OF CSG @ 2400' & SQZ W/ 50 SX. LEAVING 10 SX INSIDE CSG - 15 CUT 4 1/2" 9.5# CSG @ 1400' +/ TOH & LD CSG. 6) SPOT 50X CMT PLUG FROM 1200' - 1400', TAG PLUG. 7) SPOT 25 SX PLUG FROM 3' - 103'.	THE COMMUSSION	WHICHEVER IS GREATER OF 189 1011 12 13 74 75 75 75 75 75 75 75 75 75 75 75 75 75
12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and gwork) SEE RULE 1103. 1) MIRU PLUGGING CONTRACTOR. 2) SET CIBP @ 4100' +/-, & CAP W/ 35' OF CMT (TAG). LOAD CSG W/ M 3) SPOT 10 SX PLUG FROM 3400' - 3550'. ALL PLUGS A RESERVED A STATE OF CSG @ 2400' & SQZ W/ 50 SX. LEAVING 10 SX INSIDE CSG - 15 CUT 4 1/2" 9.5# CSG @ 1400' +/ TOH & LD CSG. 6) SPOT 50X CMT PLUG FROM 1200' - 1400', TAG PLUG. 7) SPOT 25 SX PLUG FROM 3' - 103'.	THE COMMUSSION HOURS PRIOR TO PLUGGING OPERATO BE APPROVED.	WHICHEVER IS GREATER WHICHEVER IS GREATER OF 189 1011 12 13 74 15 16 17 17 18 18 18 18 18 18 18 18 18 18 18 18 18
12Describe Proposed or Completed Operations (Clearly state all pertinent details, and gwork) SEE RULE 1103. 1) MIRU PLUGGING CONTRACTOR. 2) SET CIBP @ 4100' +/-, & CAP W/ 35' OF CMT (TAG). LOAD CSG W/ M. 3) SPOT 10 SX PLUG FROM 3400' - 3550'. ALL PLUGS A RE 4) PERF CSG @ 2400' & SQZ W/ 50 SX. LEAVING 10 SX INSIDE CSG - TO CUT 4 1/2" 9.5# CSG @ 1400' +/ TOH & LD CSG. 6) SPOT 50X CMT PLUG FROM 1200' - 1400', TAG PLUG. 7) SPOT 25 SX PLUG FROM 3' - 103'. 8) CUT OFF WELLHEAD. INSTALL P&A MARKER. RESTORE LOCATION	THE COMMUSSION HOURS PRIOR TO PLUGGING OPERATO BE APPROVED.	WHICHEVER IS GREATER WHICHEVER IS GREATER OF 189 1011 12 13 19 15 15 15 15 15 15 15 15 15 15 15 15 15
12Describe Proposed or Completed Operations (Clearly state all pertinent details, and gwork) SEE RULE 1103. 1) MIRU PLUGGING CONTRACTOR. 2) SET CIBP @ 4100' +/-, & CAP W/ 35' OF CMT (TAG). LOAD CSG W/ M 3) SPOT 10 SX PLUG FROM 3400' - 3550'. ALL PLUGS A RESERVED A 10 SX PLUG FROM 3400' - 3550'. ALL PLUGS A RESERVED A 10 SX INSIDE CSG - 10 SY OF CSG @ 2400' & SQZ W/ 50 SX. LEAVING 10 SX INSIDE CSG - 10 SPOT 50X CMT PLUG FROM 1200' - 1400', TAG PLUG. 7) SPOT 25 SX PLUG FROM 3' - 103'. 8) CUT OFF WELLHEAD. INSTALL P&A MARKER. RESTORE LOCATION INSTALL P&A MARKER. RESTORE LOCATION INSTALL P&A MARKER.	THE COMMUSSION HOURS PRIOR TO PLUGGING OPERATO BE APPROVED.	WHICHEVER IS GREATER WHICHEVER IS GREATER OF 189 1011 12 13 74 15 16 17 17 18 18 18 18 18 18 18 18 18 18 18 18 18
12Describe Proposed or Completed Operations (Clearly state all pertinent details, and gwork) SEE RULE 1103. 1) MIRU PLUGGING CONTRACTOR. 2) SET CIBP @ 4100' +/-, & CAP W/ 35' OF CMT (TAG). LOAD CSG W/ NOT SET CIBP @ 4100' +/-, & CAP W/ 35' OF CMT (TAG). LOAD CSG W/ NOT SET CIBP @ 4100' +/-, & CAP W/ 35' OF CMT (TAG). LOAD CSG W/ NOT SET CIBP @ 4100' +/ TOH & LD CSG A RESET COMPLETE OF SET CIBP @ 1400' +/ TOH & LD CSG. 5) CUT 4 1/2" 9.5# CSG @ 1400' +/ TOH & LD CSG. 6) SPOT 50X CMT PLUG FROM 1200' - 1400', TAG PLUG. 7) SPOT 25 SX PLUG FROM 3' - 103'. 8) CUT OFF WELLHEAD. INSTALL P&A MARKER. RESTORE LOCATION INSTALL P&A MARKER. RESTORE LOCATION INSTALL P&A MARKER.	THE COMMUSSION HOURS PRIOR TO PLUGGING OPERATO BE APPROVED.	MUST DE NOTBIED 24 My 4 STATIONS FOR THE CENO3 DATE 11-28-01
12Describe Proposed or Completed Operations (Clearly state all pertinent details, and gwork) SEE RULE 1103. 1) MIRU PLUGGING CONTRACTOR. 2) SET CIBP @ 4100' +/-, & CAP W/ 35' OF CMT (TAG). LOAD CSG W/ M 3) SPOT 10 SX PLUG FROM 3400' - 3550'. ALL PLUGS ARE 4) PERF CSG @ 2400' & SQZ W/ 50 SX. LEAVING 10 SX INSIDE CSG - TO 5) CUT 4 1/2" 9.5# CSG @ 1400' +/ TOH & LD CSG. 6) SPOT 50X CMT PLUG FROM 1200' - 1400', TAG PLUG. 7) SPOT 25 SX PLUG FROM 3' - 103'. 8) CUT OFF WELLHEAD. INSTALL P&A MARKER. RESTORE LOCATION SIGNATURE AND	THE COMMUSSION HOURS PRIOR TO BE APPROVED. Wedge and belief. TITLE AGENT	MUST DE NOTBIED 24 My 4 STATIONS FOR THE CENO3 DATE 11-28-01

SOUTHWEST ROYALTIES						
PROJECT State of NM Will No 22	"S" NCT-3	PAGE	OF			
Eleu 4,240 D 4330 B	16 18	1980 FME 19 Ut F, Sc. 12, Lea G, NM	1			
& Link	-3 to 103	Spudded 4/30/. Dr/g Comp \$1/3/				
13/13' put		5/14/60 Partied 4126-40, 56-6	54			
743" mt 24# H-40 mud 24# H-40 mud	1,350	16552	36, 90-1304 5015RO & 3900			
* King Fint	702 calc E 2351'	IP F 62BO	24215			
Frank	1126-4304' 4325 POTD	capped of 35 cm. f				
1/2 9.5# Jesses 1505x W/4 Pogel	4350'+0					
, vage i						

DC 10