form 3160-5 November 1983) Formeriy 9-331)		UNITED STA		SUBMIT IN TRIP	LT	Expi	get Bureau tres August DESIGNATION	31, 198	35
		U OF LAND MA			0	NM 031	5712		
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)					ir.	6. IF INDI	AN, ALLOTTE	E OR TRI	BE NAME
OIL CAB	OTHER						REEMENT NA		
NAME OF OPERATOR		······································	••••••••••••••••••••••••••••••••••••••				Iar Gray	9	Unit
Chevron	U.S.A. Inc	• •			:				100
		s. NM 8824	.0			9. WHLL R 77	10.		
P.O. BOX 670 HODDS, NM 88240 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements." See also space 17 below.)							AND POOL, OF	E WILDCA	्र <u>ु</u> इत्याद्य
At surface							iar Gray		San An
						11. SEC., T SURV	VET OR ARMA	ILK. AND	
<u>Unit H, 231</u>	D' FNL & 66	O' FEL	•			Sec 15	, T17S,	R32E	
. PERMIT NO.		15. BLEVATIONS (S				12. COUNT	T OR PARISE	13. ST.	ATE
	<u> </u>	<u> </u>		iR		Lea		NM	
			o Indicate No	ature of Notice, Repo	ort, or Ot	her Data			سريون و . مورد مورد
e i _	NOTICE OF INTEN	TION TO:			SUBSEQUE	NT REPORT	o r :		مان المراجع والمراجع
TEST WATER SHUT- Fracture treat	··· ·	CLL OR ALTER CASE IULTIPLE COMPLETE		WATER SHUT-OFF			REPAIRING W	BLL	X
		BANDON®	·	FRACTURE TREATME SHOOTING OR ACIDI	·		ALTERING CA	-	
SHOOT OR ACIDIZE			1 1 1				ABARDON MEN	T I	
REPAIR WELL		HANGE PLANS		(Other)					
EEPAIE WELL (Other) DESCRIBE INDPOSED (proposed work.) nent to this work.) OVED bad cas K-55 LT&C ca	DR COMPLETED OPEN f well is direction ing from O- asing. Lat	HANGE PLANS Clearly stand and y drilled, give a 550'. Ran ched casing	Bowen lead stub @ 55	(Other) (Notz: Repor Completion or details, and give pertime ms and measured and tru seal casing pa 50' and engaged	atch an	id 14 j	and Log for timated date all markers 0.ints 5	m.) of star and son	es perti-
REPAIR WELL (Other) DESCRIBE PROPOSED (proposed work.) nent to this work.) NOVED bad cas K-55 LT&C ca patch to 500	DR COMPLETED OPEN f well is direction ing from O- asing. Lat D psi for 3	HANGE PLANS AATIONS (Clearly sta nally drilled, give of 550'. Ran ched casing 0 minutes (1	Bowen lead stub @ 55 OK). Acid	(Other) (NoTE: Repor Completion or details, and give pertine ins and measured and tru Seal Casing Da	atch an seals.	id 14 j Test	and Log for timated date all markers o.ints 5 ed casin 082' wi	m.) e of star and son 1/2" ňg th	es perti-
COTEPAIE WELL (Other) DESCRIBE PROPOSED (proposed work.) nent to this work.) OVED bad cas K-55 LT&C ca patch to 500	DR COMPLETED OPEN f well is direction ing from O- asing. Lat D psi for 3	HANGE PLANS AATIONS (Clearly stand and y drilled, give a 550'. Ran ched casing 0 minutes (1)	Bowen lead stub @ 55 OK). Acid	(Other) (Not: Repor Completion or details, and give pertine and measured and tru seal casing pa 50' and engaged ized perforatio	atch an seals.	id 14 j Test	and Log for timated date all markers o.ints 5 ed casin 082' wi	m.) e of star and son 1/2" ňg th	es perti-
COTEPAIE WELL (Other) DESCRIBE PROPOSED (proposed work.) nent to this work.) OVED bad cas K-55 LT&C ca patch to 500	DR COMPLETED OPEN f well is direction ing from O- asing. Lat D psi for 3	HANGE PLANS AATIONS (Clearly stand and y drilled, give a 550'. Ran ched casing 0 minutes (1)	Bowen lead stub @ 55 OK). Acid	(Other) (Not: Repor Completion or details, and give pertine and measured and tru seal casing pa 50' and engaged ized perforatio	atch an seals.	id 14 j Test	and Log for timated date all markers o.ints 5 ed casin 082' wi	m.) e of star and son 1/2" ňg th	es perti-
COTEPAIE WELL (Other) DESCRIBE PROPOSED (proposed work.) nent to this work.) OVED bad cas K-55 LT&C ca patch to 500	DR COMPLETED OPEN f well is direction ing from O- asing. Lat D psi for 3	HANGE PLANS AATIONS (Clearly stand and y drilled, give a 550'. Ran ched casing 0 minutes (1)	Bowen lead stub @ 55 OK). Acid	(Other) (Not: Repor Completion or details, and give pertine and measured and tru seal casing pa 50' and engaged ized perforatio	atch an seals.	id 14 j Test	and Log for timated date all markers o.ints 5 ed casin 082' wi	m.) e of star and son 1/2" ňg th	es perti-
COTEPAIE WELL (Other) DESCRIBE PROPOSED (proposed work.) nent to this work.) OVED bad cas K-55 LT&C ca patch to 500	The COMPLETED OPER f well in direction ing from O- asing. Lat D psi for 3 % NEFE HCL.	HANGE PLANS Autions (Clearly stand) ally drilled, give a 550'. Ran ched casing 0 minutes (1 Returned	Bowen lead stub @ 55 OK). Acid to product	(Other) (Not: Repor Completion or details, and give pertine and measured and tru seal casing pa 50' and engaged ized perforatio	atch an seals.	id 14 j Test	and Log for timated date all markers o.ints 5 ed casin 082' wi	m.) e of star and son 1/2" ňg th	es perti-
EEPAIR WELL (Other) DESCRIBE PROPOSED (proposed work.) nent to this work.) OVED bad cas K-55 LT&C ca patch to 500	The COMPLETED OPER f well in direction ing from O- asing. Lat D psi for 3 % NEFE HCL.	HANGE PLANS AATIONS (Clearly stand and y drilled, give a 550'. Ran ched casing 0 minutes (1)	Bowen lead stub @ 55 OK). Acid to product	(Other) (Not: Repor Completion or details, and give pertine and measured and tru seal casing pa 50' and engaged ized perforatio	atch an seals.	id 14 j Test	and Log for timated date all markers o.ints 5 ed casin 082' wi	m.) e of star and son 1/2" ňg th	es perti-
EEPAIR WELL (Other) DESCRIBE PROPOSED (proposed work.) nent to this work.) OVED bad cas K-55 LT&C ca patch to 500	The COMPLETED OPER f well in direction ing from O- asing. Lat D psi for 3 % NEFE HCL.	ATIONS (Clearly standy drilled, give a 550'. Ran i ched casing 0 minutes (i Returned CEPTED FOR	Bowen lead stub 0 55 OK). Acid to product	(Other) (Not: Repor Completion or details, and give pertine and measured and tru seal casing pa 50' and engaged ized perforatio	atch an seals.	ion Beport acluding es depths for D = 4 9/23/8	and Log for timated date all markers o.ints 5 ed casin 082' wi 6 - 9/30	m.) e of star and son 1/2" ng th 0/86.	es perti-
EEPAIR WELL (Other) DESCRIBE PROPOSED (proposed work.) nent to this work.) OVED bad cas K-55 LT&C ca patch to 500	The COMPLETED OPER f well in direction ing from O- asing. Lat D psi for 3 % NEFE HCL.	ATIONS (Clearly standy drilled, give a 550'. Ran i ched casing 0 minutes (i Returned CEPTED FOR	Bowen lead stub @ 55 OK). Acid to product	(Other) (Not: Repor Completion or details, and give pertine and measured and tru seal casing pa 50' and engaged ized perforatio	atch an seals.	ion Beport acluding es depths for D = 4 9/23/8	and Log for timated date all markers o.ints 5 ed casin 082' wi	m.) e of star and son 1/2" ng th 0/86.	es perti-
Cother) DESCRIBE PROPOSED (proposed work.) nent to this work.) OVED bad cas K-55 LT&C ca patch to 50(ACC	HANGE PLANS ATTIONS (Clearly stand) S50'. Ran Sched casing O minutes (I Returned CEPTED FOR Suc OCT 24	Bowen lead stub @ 55 OK). Acid to product RECORD	(Other) (Not: Repor Completion or details, and give pertine and measured and tru seal casing pa 50' and engaged ized perforatio	atch an seals.	ion Beport acluding es depths for D = 4 9/23/8	and Log for timated date all markers o.ints 5 ed casin 082' wi 6 - 9/30	m.) e of star and son 1/2" ng th 0/86.	es perti-
COTEPAIE WELL (Other) DESCRIBE PROPOSED (proposed work.) nent to this work.) OVED bad cas K-55 LT&C ca patch to 500	ACC	ATIONS (Clearly standy drilled, give a 550'. Ran i ched casing 0 minutes (i Returned CEPTED FOR	Bowen lead stub @ 55 OK). Acid to product RECORD	(Other) (Not: Repor Completion or details, and give pertine and measured and tru seal casing pa 50' and engaged ized perforatio	atch an seals.	ion Beport acluding es depths for D = 4 9/23/8	and Log for timated date all markers o.ints 5 ed casin 082' wi 6 - 9/30	m.) e of star and son 1/2" ng th 0/86.	es perti-
COTEPAIE WELL (Other) DESCRIBE PROPOSED (proposed work.) nent to this work.) OVED bad cas K-55 LT&C ca patch to 500	ACC	HANGE PLANS ATTIONS (Clearly stand) S50'. Ran Sched casing O minutes (I Returned CEPTED FOR Suc OCT 24	Bowen lead stub @ 55 OK). Acid to product RECORD	(Other) (Not: Repor Completion or details, and give pertine and measured and tru seal casing pa 50' and engaged ized perforatio	atch an seals.	ion Beport acluding es depths for D = 4 9/23/8	and Log for timated date all markers o.ints 5 ed casin 082' wi 6 - 9/30	m.) e of star and son 1/2" ng th 0/86.	es perti-
COTEPAIE WELL (Other) DESCRIBE PROPOSED (proposed work.) nent to this work.) OVED bad cas K-55 LT&C ca patch to 500	ACC	HANGE PLANS ATTIONS (Clearly stand) S50'. Ran Sched casing O minutes (I Returned CEPTED FOR Suc OCT 24	Bowen lead stub @ 55 OK). Acid to product RECORD	(Other) (Not: Repor Completion or details, and give pertine and measured and tru seal casing pa 50' and engaged ized perforatio	atch an seals.	ion Beport acluding es depths for D = 4 9/23/8	and Log for timated date all markers o.ints 5 ed casin 082' wi 6 - 9/30	m.) e of star and son 1/2" ng th 0/86.	es perti-
REPAIR WELL (Other) DESCRIBE PROPOSED OF proposed work. Noved bad cas K-55 LT&C ca patch to 500 0 gallons 159	ACC	HANGE PLANS MATIONS (Clearly str nally drilled, give a 550'. Ran ched casing 0 minutes (1 Returned CEPTED FOR QCT 2 4 RLSBAD, NEW	Bowen lead stub @ 55 OK). Acid to product RECORD	(Other) (Not: Repor Completion or details, and give pertine and measured and tru seal casing pa 50' and engaged ized perforatio	atch an seals.	ion Beport acluding es depths for D = 4 9/23/8	and Log for timated date all markers o.ints 5 ed casin 082' wi 6 - 9/30	m.) e of star and son 1/2" ng th 0/86.	es perti-
EEPAIE WELL (Other) DESCRIBE PROPOSED of proposed work.) NOVED bad cas K-55 LT&C ca patch to 500 0 gallons 155	ACC	HANGE PLANS MATIONS (Clearly str nally drilled, give a 550'. Ran ched casing 0 minutes (1 Returned CEPTED FOR QCT 2 4 RLSBAD, NEW true and correct	Bowen lead stub 0 55 OK). Acid to product RECORD 1986	(Other) (Not: Repor Completion or details, and give pertine and measured and tru seal casing pa 50' and engaged ized perforatio	atch an seals. ons 374 formed	ion Beport acluding es depths for 0' - 4 9/23/8	and Log for timated date all markers oints 5 ed casin 082' wi 6 - 9/30 2 1986 2 2 1986	m.) e of star and zon 1/2" ng th 0/86.	
EEPAIE WELL (Other) DESCRIBE INDOPOSED OF PRODOSED work.) NOVED bad cas: K-55 LT&C ca patch to 500 0 gallons 159	The foregoing is	HANGE PLANS MATIONS (Clearly str nally drilled, give a 550'. Ran ched casing 0 minutes (Returned CEPTED FOR QUCT 2 4 RISBAD, NEW true and correct	Bowen lead stub 0 55 OK). Acid to product RECORD 1986 MEXICO Dril	(Other) (Not:: Repor Completion or details, and give pertine ins and measured and tru is seal casing pa io' and engaged ized perforation cion. Work pertonal	atch an seals. ons 374 formed	ion Beport acluding es depths for D = 4 9/23/8	and Log for timated date all markers oints 5 ed casin 082' wi 6 - 9/30 2 1986 2 2 1986	m.) e of star and zon 1/2" ng th 0/86.	
REPAIR WELL (Other) DESCRIBE PROPOSED (proposed work.] nent to this work.) NOVEd bad cas: K-55 LT&C ca patch to 50(00 gallons 15) I hereby certify that BIGNED	CAF	HANGE PLANS MATIONS (Clearly str nally drilled, give a 550'. Ran ched casing 0 minutes (1 Returned CEPTED FOR QCT 2 4 RLSBAD, NEW true and correct Use)	Bowen lead stub 0 55 OK). Acid to product RECORD 1986 MEXICO Dril	(Other) (Not:: Repor Completion or details, and give pertine ins and measured and tru is seal casing pa io' and engaged ized perforation cion. Work pertonal	atch an seals. ons 374 formed	ion Beport acluding es depths for 0' - 4 9/23/8	and Log for timated date all markers oints 5 ed casin 082' wi 6 - 9/30 2 2 1986 10-21-	m.) e of star and zon 1/2" ng th 0/86.	

and a start of the second start

•

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.