

**UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY**

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 029509-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

MCA

8. FARM OR LEASE NAME

MCA Unit

9. WELL NO.

43

10. FIELD AND POOL OR WILDCAT

Baish Maj. Pearsall Field

Maljamar San Andres Pool

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 21, T-17S, R-32E

12. COUNTY OR PARISH

Lea

13. STATE

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL GAS WELL OTHER

MAR 9 12 33 PM '65

2. NAME OF OPERATOR
Continental Oil Company

3. ADDRESS OF OPERATOR
Box 460, Hobbs, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
At surface 1980' FNL & 1980' FEL of Sec. 21, T-17S, R-32E, Lea County, New Mexico, NMPM.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4036' DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL

PULL OR ALTER CASING
MULTIPLE COMPLETE
ABANDON*
CHANGE PLANS

(Other) Repair Casing Leak

SUBSEQUENT REPORT OF:

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING

REPAIRING WELL
ALTERING CASING
ABANDONMENT*

(Other)
(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

It is proposed to repair a casing leak in the subject well using the following procedure:

1. Pull Tubing
2. Fill open hole and casing from 4108' TD to 3,400' W/sand.
3. Cement through perforations @ 2200' W/100 sx cement using cement retainer.
4. Drill out cement and retainer and test cement job. Re-squeeze if necessary.
5. Drill and clean out to 4,100' and place well back on production.

Your approval of the above work is requested.

18. I hereby certify that the foregoing is true and correct

SIGNED ROBERT GAULT III

TITLE Staff Supervisor

DATE 2-23-65

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

USGS-5, NMOCC-2, JM

*See Instructions on Reverse Side

