

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other Instructions
reverse side)

Form approved
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR CONOCO INC.	8. FARM OR LEASE NAME Baish A
3. ADDRESS OF OPERATOR P. O. Box 460, Hobbs, N.M. 88240	9. WELL NO. 8
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit I	10. FIELD AND POOL, OR WILDCAT Mahamar Abo
14. PERMIT NO. 30-025-00622	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 21-175-32E
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH Lea
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETION ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☒
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	
(Other) ☐		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- ① Already on well for casing repair, P & A work commenced 3-5-86
- ② Set cmt retainer @ 2973'; load csg to 500 psi and pumped 500 sxs class "H" string out retainer
- ③ Shot 4 holes @ 2900', set ret @ 2782', test backside to 500 psi. Pumped 500 sxs class "H" cmt. string out of retainer & spot 3sxs on top.
- ④ *Spotted 50' cmt. in top of 7" csg.
- ⑤ Cut wellhead off and install P & A marker. Rig down on 3-7-86.
- * (3a) 100' plug 940' to 840'

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Administrative Supervisor DATE 3-24-86

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE 9-23-86

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side