

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

LEASE DESIGNATION AND SERIAL NO.
LC-029509A
IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER <u>Injection</u>	7. UNIT AGREEMENT NAME <u>MOA Unit</u> <u>BTY 2</u>
2. NAME OF OPERATOR <u>Conoco Inc.</u>	8. FARM OR LEASE NAME
3. ADDRESS OF OPERATOR <u>P.O. Box 460 - Hobbs, NM 88240</u>	9. WELL NO. <u>#40</u>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface <u>Unit E 2310' FNL + 330' FWL</u>	10. FIELD AND POOL, OR WILDCAT <u>Malpais 6 SA</u>
14. PERMIT NO. <u>30-025-00635</u>	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>Sec. 22, T17S, R32E</u>
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH <u>Lea</u>
	13. STATE <u>NM</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other)

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) Repair Communications

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

3/29 MIRU. NDWH. NUBOP. WITH w/retrieving head, 5" mod. R. pkr + W.S. Set pkr in top of liner @ 2191'. Flow coming up W.S. Release pkr. Latched RBP. Open K-Valve, Equalized, Worked up + down hole. Reset RBP @ 3537'. Released. Set pkr. @ 3534'. Test RBP to 1000 # held. Test csg. to 500 # held. Released pkr. Circ. pkr fluid. POOH w/w.s. + pkr. Return to rig. See attached chart well-TA

ACCEPTED FOR RECORD

AK

APR 10 1990

18. I hereby certify that the foregoing is true and correct

CARLSBAD, NEW MEXICO

SIGNED

H.A. Ingram

TITLE

Conservation Coordinator

DATE

4/4/90

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side