16.

"TED STATES SUBMIT IN TRI "CATE"

Form approved. Radaut Raman No. 42-R1424.

L I OF THE INTERIOR (Other instruction)	5. LEASE DESIGNATION AND SERIAL N
EOLOGICAL SURVEY	TC 0=9152 (3)

	ML I OF THE INTERIOR verse side) SEOLOGICAL SURVEY	5. LEASE DESIGNATION AND SERIAL NO. LC 0-9152 (3)
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
OIL GAS GAS OTHER		7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR		8. FARM OR LEASE NAME
Atlantic Richfield	Company	Johns "B" DE
3. ADDRESS OF OPERATOR	· · · · · · · · · · · · · · · · · · ·	9. WELL NO.
P. O. Box 1978, Ros	swell, New Mexico 88201	. 3
4. LOCATION OF WELL (Report location of See also space 17 below.) At surface	learly and in accordance with any State requirements.*	10. FIELD AND POOL, OR WILDCAT Maljamar Gravburg
1980' FSL & 1980' F	FWL, Unit K	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 24-T17S-R32E
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, BT, GR, etc.)	
		12. COUNTY OR PARISH 13. STATE
	<u> 4070'</u> DF	Lea N. Mex.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data MOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF REPAIRING WELL PRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT ALTERING CASING SHOOT OR ACIDIZE ABANDON* SECOTING OR ACIDIZING ABANDONMENT* (Other) Shut-in REPAIR WELL CHANGE PLANS (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The electric motor on this well is in need of repairs. The well has declined in production to 2 BOPD and 85 BWPD and the cost of repairs to the electric motor would be uneconomical. This well was shut-in on March 29, 1971. This well has remained shut-in the entire month of October, 1971 for reason as above.

18. I hereby certify that the foregoing is true and correct Sr. Acctg. Clerk 11-3-71 DATE (This space for Federal or State office use)

APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

3

*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY HOBBS, NEW MEXICO

RECEIVED

NOV 161971 OIL CONSERVATION COMM. HOBBS, N. M.