N. M. CR. CONS. C' RESSION

P. O. BOX 1980

·		OF THE INTE	KIUK	Budget Bureau No. 1004-0135
	BUREAU OF LA	ND MANAGE	MENT	Expires: March 31, 1993 5. Lease Designation and Serial No.
	SUNDRY NOTICES A	NO DEDODES	O \$1.147 = 1.1	LC 058697B
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals SUBMIT IN TRIPLICATE				
				7. If Unit or CA, Agreement Designation
Type of Well Oil Well Well Well				
2. Name of Operator				8. Well Name and No. MCA UNIT #356
Conoco Inc. 3. Address and Telephone No.				9. API Well No.
10 Desta Drive STE 100W, Midland, TX 79705 (915)686-5424				30-025-00695
4 Location of Well (Footage, Sec., T., R., M., or Survey Description)				10. Field and Pool, or Exploratory Area MALJAMAR (G-SA)
1295° FSL & 1245° FEL, SEC. 25, T-17S, R-32E, UNIT LTR 'P'				11. County or Parish, State
2. CHECK A	PPROPRIATE BOX(s)	TO INDICATE	NATURE OF NOTICE DE	LEA CO. NM.
TYPE OF S	UBMISSION	HOICATE	NATURE OF NOTICE, RE	
Notice of I		XX A	TYPE OF ACT	ION
			bandonment ecompletion	Change of Plans
XX Subsequent	t Report		ugging Back	New Construction Non-Routine Fracturing
Final Aban	idonment Notice		asing Repair Itering Casing	Water Shut-Off
			ther	Conversion to Injection Dispose Water
				(Note: Report results of multiple completion on Wei
3. Describe Proposed or Comp	eted Operations (Clearly sees all			Completion of Recompletion Report and Log form.
 Describe Proposed or Comp. give subsurface location 	leted Operations (Clearly state all pert ins and measured and true vertical de	inent details, and give p pths for all markers an	ertinent dates, including estimated date of st d zones pertinent to this work.)*	Completion or Recompletion Report and Log form tarting any proposed work. If well is directionally drilled
2-23-93 MIRU.	RIH W/ 2 3/8" TEG	TAG CIPB @	3960', SPOT 10 SX CMT	tarting any proposed work. If well is directionally drille
2-23-93 MIRU.	RIH W/ 2 3/8" TEG	TAG CIPB @ OH. FILL HO CUT OFF WEL	3960', SPOT 10 SX CMT	FROM 3960 TO 3900 MT @ 1198 CIRC 210 SX AT AND INSTALL P&A MARKER.
2-23-93 MIRU. PUH TO 2400 SF CMT FROM 1198 2-25-93 RMDO.	RIH W/ 2 3/8" TBG POT 200 SX CMT, POC TO SURFACE POOH. going is true and correct	TAG CIPB @ OH. FILL HO CUT OFF WEL	Joed as to pay the well to go under bond is remined until	FROM 3960 TO 3900 MT @ 1198 CIRC 210 SX MT AND INSTALL P&A MARKER.
2-23-93 MIRU. PUH TO 2400 SF CMT FROM 1198 2-25-93 RMDO. I hereby certify that the fore Signed (This space for Federal or St	RIH W/ 2 3/8" TBG POT 200 SX CMT, POC TO SURFACE POOH. going is true and correct	TAG CIPB @ OH. FILL HO CUT OFF WEL	3960*, SPOT 10 SX CMT LE W/ MUD. RIH TAG C LHEAD, FILL CSG W/ CM	FROM 3960 TO 3900 MT @ 1198 CIRC 210 SX MT AND INSTALL P&A MARKER.

*See instruction on Reverse Side

5