	Form 9–331	Form Approved. Budget Bureau No. 42–R1424
	UNITED STATES	5. LEASE
	DEPARTMENT OF THE INTERIOR	LC-058408 (a)
	GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use Form 9-331-C for such proposals.)	7. UNIT AGREEMENT NAME MCA Unit
		8. FARM OR LEASE NAME
	1. oil well gas well other	9. WELL NO.
	2. NAME OF OPERATOR	142
	CONOCO INC.	10. FIELD OR WILDCAT NAME
	3. ADDRESS OF OPERATOR P. O. Box 460, Hobbs, N.M. 38240	Maljamar (G-SA)
	 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
1 1 A.	AT SURFACE: 1980'FNL \$ 1980'FEL AT TOP PROD. INTERVAL:	Sec. 26, T-175, R-32E 12. COUNTY OR PARISH 13. STATE Lea NM
	AT TOTAL DEPTH:	14. API NO.
	16. CHECK APPBOPRIATE BOX TO INDICATE NATURE OF NOTICE, BEPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
	REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF	(NOTE: Report results of multiple completion or zone change on Form 9–330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

We propose to CO the subject well to 4300' from the old TO of 4180' to recover oil from the San Andres 7th & 9th zones.

Subsurface Safety Valve: Manu. and Ty	pe	Set @ Ft.
18. I hereby certify that the foregoing i SIGNED MMA Futterfue	s true and correct	_ DATE February 5,1981
Y	(This space for Federal or State office us	e)
APPROVED BY		DATE
	*See Instructions on Reverse Side	APPROVED FED 9 1981 DISTRICT SUPERVISOR

NEW MEXICO OIL CONSERVATION COMMISSION WELL LOCATION AND ACREAGE DEDICATION PLAT

.

ŝ

Form C-102 Supersedes C-128 Effective 1-1-65

All distances must be from the outer boundaries of the Section.							
Conoco I	ИС.		Lease /	NCA Uni	4	Well No. 142	
Unit Leffer Secti	ion T	ownship	Runc		County		
	26	17 south	2 .	32 east	Lea	······································	
1980 teet from the North line and 1980 feet from the East line							
Ground Level Elev:	Producing Format	tion	[Pool	ljamar (G		Dedicated Acreage:	
	San Ar					40 Acres	
1. Outline the acreage dedicated to the subject well by colored pencil or hachure marks on the plat below.							
2. If more than one lease is dedicated to the well, outline each and identify the ownership thereof (both as to working interest and royalty).							
3. If more than one dated by commu	e lease of diffe nitization, unit	erent ownership is ization, force-poo	s dedicated ling. etc?	l to the well, h	ave the interests	of all owners been consoli-	
Yes	No If answ	ver is "yes," type	of consoli	dation			
this form if nece	essary.)					dated. (Use reverse side of	
No allowable wi forced-pooling, o sion.	ll be assigned or otherwise) or	to the well until a until a non-standa	ll interests ard unit, el	s have been co iminating such	insolidated (by co interests, has bee	mmunitization, unitization, n approved by the Commis-	
	1					CERTIFICATION	
				1			
	1			1		r certify that the information con- perein is true and complete to the	
	1			1	11	my knowledge ond belief.	
		`0		l			
	1	861		I	Name		
	┼╸·── ── ── ── ·	+	=		When	1. Duterbull.	
	1	1	i		Position		
	} 1	1	 		Admini	strative Supervisor	
	i	1 4		1980'	Company	T	
	1		1		Date	oco Inc.	
	1		1		Fe	bruery 2, 1981	
	l		<u> </u>				
	1		1		1 hereby	v certify that the well location	
	I					n this plat was plotted from field	
	1		. 1		# 1	octual surveys made by me or	
	1		1		under my	supervision, and that the same	
	1		I		11	and correct to the best of my	
					knowled	ge and belief.	
	•						
	ł				Date Surve	yed	
	I				Registered	Professional Engineer	
	ł		1		and/or Lan		
	1		1				
		!			Certificate	No.	
0 330 086 0 Et 00' 088 0EE 0	20 1650 1980 2	310 2640 200	0 1500	1000 500			

MCA NO. 142

DEEPENING AND STIMULATION

RECOMMENDED PROCEDURE:

- 1. Rig up pulling unit. Install BOP.
- 2. Pull out rods & tubing.
- 3. GIH w/retrievable BP and pkr. on workstring, and pressure test casing to 1000 psi. If a casing leak is indicated, a squeeze procedure will be prepared immediately. POOH w/BP and pkr.
- 4. GIH w/6-1/4" drilling bit, and drill collars on workstring. Drill out to 4300'. (Fishing junk out of hole could be considered, depending on type of junk encountered by drill bit.) Use clean produced water during deepening. POOH.
- 5. Run Gamma Ray, Caliper, and Sidewall Neutron Porosity logs from 4300' to 3600'.
- 6. Stimulation procedure will be prepared after logs have been run.

	N
ENGINEER	DATE
SUPERVISING PRODUCTION ENGINEER	DATE
DIVISION ENGINEER	DATE
DRILLING SUPERVISOR	DATE

