

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions on reverse side)Form approved
Project Bureau No. 42-11134

5. LEASE DESIGNATION AND SERIAL NO.

LC-057210

6. IF INDIAN, ALLOTTEE OR TRUST NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR	MCA
3. ADDRESS OF OPERATOR	8. FARM OR LEASE NAME
P. O. Box 460, Hobbs, New Mexico 88240	MCA UNIT
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface	9. WELL NO.
660' FNL : 660' FWL of Section 28, T-17S, R-32E, in Lea County, N. Mex.	114
14. PERMIT NO.	10. FIELD AND POOL, OR WILDCAT
15. ELEVATIONS (Show whether DE, KY, CR, etc.)	11. SEC., T., R., M., OR BELL AND SURVEY OR AREA
3986' DF	Sec. 28, T-17S, R-32E
12. COUNTY OR PARISH	13. STATE
LEA	N. MEX.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

It is proposed to blast frac this well by the following procedure.

Run 4 1/4" bit and clean out to TD. Place approx 1940# explosive from 4071' to 4005'. Run cannister with 70# explosive from 4005' to 3995'. Dump pea gravel from 3995' to 3950' and 4180# explosive from 3950' to 3726'. Run another cannister with 42# explosive from 3726' to 3720'. Set pea gravel and calseal plugs to 3440'. Observe detonation. Clean out to TD and place well back on production work to commence 12-15-69

18. I hereby certify that the foregoing is true and correct

SIGNED

M. E. Yeakley

TITLE

Adm. Section Chief

DATE

12-11-69

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

USGS-5 FILE

MCA Partners

*See Instructions on Reverse Side

APPROVED

DEC 12 1969

ARTHUR R. BROWN
DISTRICT ENGINEER