Form 3160-5 (June 1990)

# **UNITED STATES** DEDARTMENT OF THE INTEDIOR

# N., THE CONS. COMMISSION P.O. BOX 1980 HOBBS NEW MEXICO 88240

Budget Bureau No. 1004-0135

Julie 1770)	DEPARTME	AT OF THE INTERIOR	Expires: March 31, 1993
	BUREAU OF	LAND MANAGEMENT	5. Lease Designation and Serial No.
CUMPRY NOTICES AND REPORTS ON WELLS			LC 029410A
SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals			6. If Indian, Allottee or Tribe Name
	SUBMIT	7. If Unit or CA, Agreement Designation	
1. Type of			
			8. Well Name and No.
2. Name of Operator			MCA Unit No. 158
Conaco. Inc.			9. API Well No.
3. Address and Telephone No.			30-025-00761
10 Desta Dr. Ste 100W, Midland, TX 79705			10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			Maljamar Grayburg/SA
1980' FNL & 660' FWL			11. County or Parish, State
Sec. 29, T-17S, R-32E			Lea
12	CHECK APPROPRIATE BOX	(s) TO INDICATE NATURE OF NOTICE, REPOR	RT, OR OTHER DATA
	TYPE OF SUBMISSION	TYPE OF ACTION	
	Notice of Intent	Abandonment	Change of Plans
		Recompletion	New Construction
	Subsequent Report	Plugging Back	Non-Routine Fracturing
	•	Casing Repair	Water Shut-Off
	Final Abandonment Notice	Altering Casing	Conversion to Injection
		Other Casing Integrity	Dispose Water
		Test	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form)
13. Describe	Proposed or Completed Operations (Clearly state a e subsurface locations and measured and true verti	Ill pertinent details, and give pertinent dates, including estimated date of starting cal depths for all markers and zones pertinent to this work.)*	any proposed work. If well is directionally drilled.

It is proposed to prepare this well for temporary abandonment by the following procedure:

- POOH with producing equipment. Set 5 1/2" packer @ 3730'. Notify the BLM 48 hours prior to pressure testing. Pressure test casing to 500 psi for 30 minutes. Load the hole with packer fluid & POOH with workstring.

14. I hereby certify that the foregoing is Sr. Conservation Coordinator (This space for Federal or State office use) Petroleum Engineer Approved by (ORIG. SGD.) Title Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Rev: 1/12/95)

### BUREAU OF LAND MANAGEMENT CARLSBAD RESOURCE AREA

# Temporary Abandonment of Wells on Federal Lands

# Conditions of Approval

Temporary Abandonment (TA) status approval requires: A) <u>Successful Casing Integrity Test</u> and, B) Successful Bradenhead Test.

Any temporary abandonment request must be submitted on a Sundry Notice (Form 3160-5), one (1) original signature and five (5) copies, and include the following:

- 1. Justification why the well should be temporarily abandoned rather than permanently plugged and abandoned.
- 2. Description of the temporary abandonment procedure.
- 3. A complete wellbore diagram shown as temporarily abandoned.
  4. The anticipated date the operations will occur.

Contact the appropriate BLM office at least 48 hours prior to the scheduled Casing Integrity and the Bradenhead Tests. For wells in Eddy County call (505) 887-6544; for wells in Lea County call (505) 393-3612.

#### A) Casing Integrity Test for TA:

- Install an isolation device (such as a retainer or bridge plug) within 50' to 100' of the top perforation or cement plug that extends at least 50' above each set of open perforations. Unless prior approval is granted by the Authorized Officer, fill the well bore with conditioned, noncorrosive fluid and shut-in at the surface. If a cement plug is used, the top of the cement must be verified by tagging. If the wellbore had more than one producing horizon, the lower set(s) of perforations or open hole must meet the requirements for permanent plug to abandonment, unless justification is provided by the operator not to do so.
- A test demonstrating casing mechanical integrity is required. An approved method is a pressure test of the casing and uppermost plug. The pressure test conducted shall be a minimum of 500 psi surface pressure with less than 10 percent pressure drop within thirty (30) minutes. In no event shall the pressure test required exceed seventy (70) percent of the internal yield of In the case of an unsuccessful test, the operator shall either correct the problem the casing. or plan to plug and abandon the well. Alternative methods demonstrating casing mechanical integrity may be approved by the Authorized Officer on a case-by-case basis.

# B) Bradenhead Test for TA:

- 1. Record the pressure measured on each casing string, including intermediate casing, using deadweight or calibrated pressure gauge.
- 2. Open the bradenhead valve to the atmosphere. If gas or water flow is observed or indicated, flow the bradenhead for a minimum of fifteen (15) minutes and record pressures at five (5) minute intervals on the production, intermediate and surface casing. Describe in detail any fluids flowing from the bradenhead including measured or estimated rates of flow. A water and/or gas applied any be required. analysis may be required.

Wells that successfully pass the casing integrity test and the bradenhead test will be approved for Temporary Abandonment (TA) status for 12 months provided that the operator:

- 1.Submits within thirty (30) days a subsequent Sundry Notice (one (1) original signature and five (5) copies) requesting TA approval,
- 2. Attaches a clear copy or the original of the pressure test charts,
- If the well does not pass the casing integrity test and/or the bradenhead test, then the operator shall within 90 days submit to BLM for approval one of the following:
- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

