

Energen Resources

State "I" # 1
Lea County, New Mexico

Elevation GL: 4205'
Elevation DF: 4215'
Elevation KB: 4216'
Location: 660' FSL, 1980' FWL,
Sec 4, T - 15 - S, R - 33 - E
Spudded: 01/28/53
Completed: 04/01/53
API #: 30 - 025 - 01224

Current status: Shut In
12/18/2002

Surface csg:
13 3/8", 35.6#, J-55,
@ 296' w/ 300 sks cmt,
17 1/2" hole

Surface csg shoe: 296' (01/28/53)

TOC @ 916 by TS

Collapsed Casing: 2523'-2740' (12/98)
Not Repaired--FISH IN HOLE BELOW 2740'
Fished 13 days, unable to recover fish. 12/98

Intermediate csg shoe: 4235' (02/06/53)

Probable Production Source--Holes 4950-5000'
(Noted in Nabla Reports)

Intermediate csg:
8 5/8", 32#, J - 55,
@ 4235', w/ 1500 sks cmt,
12-1/4' hole
TOC @ 916' by TS

TOC Unknown (Squeeze)
Csg leak: 5106-37' sqz'd 150 sks cmt (03/19/62)

TOC 5 1/2": 7028' (03/24/53) by TS

CIBP: 9600' (08/28/80)

Perfs: 9740, 46, 69, 93, 9817, 24, 9918', (8/28/80)
9880-9905, 9944-60, 164 holes (4/53)

Production csg:
5 1/2", 15.5# & 17#, J-55 & N-80 LT&C
@ 10,045' w/ 600 sks 50/50 Poz
TOC @ 7028' by TS
7-7/8" hole

PBTD: 10,054' (07/15/85)
Production csg shoe: 10,050' (03/24/53)
TD: 10,050' (03/24/53)