

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

E-881

7. Lease Name or Unit Agreement Name

NORTHEAST MALJAMAR UNIT

8. Well No.

1

9. Pool name or Wildcat

Maljamar Wolfcamp

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

PENROC OIL CORPORATION

3. Address of Operator

P.O. Box 5970, HOBBS, NM 88241-5970

4. Well Location

Unit Letter D : 810 Feet From The NORTH Line and 610 Feet From The WEST Line

Section 5 Township 17 S Range 33 E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to rig up workover rig. LD rods & pump. Unload pkr & TOH w/ thg.
Run & set CIBP @ 10,300' (Top perf: 10,390') - Originally TOC was
9100'. 8/92 squeezed 350 SXS. @ 7356'. Previous oper. squeezed 300 SXS.
4869' - 4899'. Vertilog shows 80% metal loss in csg. from 5000' - 6000'.
Cut & pull 5 1/2" csg. 4500'±. LD same. TTH w/ thg - spot cement across
CIBP and load csg w/ cement to top of 5 1/2" cut-off. & 50' out. Circulate
above cut-off w/ gelled mud. Spot 100' cement plug 300'-400' - 10 SX
plug @ surface. Install dry hole marker. Clean up location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

M. G. Merchant

TITLE

President

DATE

12/28/92

TYPE OR PRINT NAME

M. G. Merchant

TELEPHONE NO.

(505) 397-3596

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY

TITLE

DATE

DEC 30 '92

CONDITIONS OF APPROVAL, IF ANY: