## State of New Mexico Energy, Minerals & Natural Resources Department

Form C-103 Revised 1-1-89

District Office	Energy, Witherars & Natural Reso	ources Department	Revised 1-1-03
DISTRICT I	OIL CONSERVATION	DIVISION [	WELL API NO.
P. O. Box 1980, Hobbs, NM 88240	P. O. Box 2088		30-025-01502
DISTRICT II	Santa Fe, NM 87504	- I	5. Indicate Type of Lease
P. O. Drawer DD, Artesia, NM 88210	Santa 1 C, 14141 67304	-2000	STATE X FEE
DISTRICT III			6. State Oil & Gas Lease No.
1000 Rio Brazos Rd., Aztec, NM 87410			B-2148
SUNDRY NOTICES AND REPORTS ON WELLS			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT"  (FORM C-101) FOR SUCH PROPOSALS.)			Caprock Maljamar Unit
1 Type of Well:			
OIL GAS TO WIND WIND			
WELL WELL OTHER WIW  2. Name of Operator			8. Well No.
The Wiser Oil Company		!	43
3. Address of Operator			9. Pool name or Wildcat
P.O. Box 2568 Hobbs, New Mexico 88241 (505) 392-9797			Maljamar Grayburg San Andres
4. Well Location			
North 1090 T			
Unit Letter <u>B</u> : 660 Feet From The <u>North</u> Line and <u>1980</u> Feet From The <u>East</u> ine			
Section 20 Township 17S Range 33E NMPM Lea Courty			
10. Elevation (Show whether DF, RKB, RT, CF, etc.)			
4211' GR			
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO SUBSEQUENT REPORT OF.			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK LATERING CASING			
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT			
PULL OR ALTER CASING CASING TEST AND CEME			т јов 🔲
OTHER:		THED:	
OTHER:  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed			
worl.) SEE RULE 1103.			
Wiser request approval to plug and abandon the well by the procedure listed below.			
1 NORTH CACODD © 4150). Down 10 down and an also			
<ol> <li>MIRU. Set CIBP @ 4150'. Dump 10 sks. cmt. on plug.</li> <li>Circulate mud.</li> </ol>			
<ol> <li>Set cmt. plug w/25 sks. @ 1550'.</li> <li>Perforate csg. @ 275' &amp; circulate cma. to surface.</li> </ol>			
	late cma. to surface.		
5 Install dry hole marker.			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE Mike amis 31:17	737	TITLE Superintende	DATE September 14, 1999
TYPE OR PRINT NAME Mike Jones			TELEPHONE NO. 392-9797
(This space for State Use)		· · · · · · · · · · · · · · · · · · ·	
(This space for State Use)  UMIGINAL SIGNED B	Y		
APPROVED BY GARY WINK	•	TITLE	DATE 9-15-99
FIELD REP. II		_ TITLE	DATE
the control of the co			