

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
E 2509	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
Tenneco Oil Company		Kennitz Wolfcamp
3. Address of Operator		9. Well No.
7990 IH 10 West, San Antonio, TX 78230		15
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER <u>D</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM		Kennitz Lower Wolfcamp
THE <u>West</u> LINE, SECTION <u>29</u> TOWNSHIP <u>16S</u> RANGE <u>34E</u> NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
		Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Clean out well to PBTD. Set RBP at 10,740'. Perforate 10,704' to 10,738' with a 4" casing gun loaded with 2 JSPF. Perforate in acid. Acidize 10,704' to 10,738'. Swab back load. Retrieve RBP. Return well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Robert M. Attie* TITLE Production Engineering Supv. DATE 30 May 1984

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT I SUPERVISOR TITLE DATE JUN 4 1984

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
JUN 4 1984
O.C.D.
HOBBS OFFICE