

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name <u>Kennitz (WC) Unit</u>
2. Name of Operator <u>Tenneco Oil Company</u>	8. Farm or Lease Name <u>Kennitz Unit</u>
3. Address of Operator <u>Box 1031 Midland, Texas 79701</u>	9. Well No. <u>25</u>
4. Location of Well UNIT LETTER <u>G</u> 1980 FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>29</u> TOWNSHIP <u>14S</u> RANGE <u>34E</u> NMPM.	10. Field and Pool, or Wildcat <u>Kennitz WC</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>4132 KB</u>	12. County <u>Lea</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-15-70
1. Clean out hole to 10810 (Drill cement 10772-10810)
2. Perforate 10764-70 and 10783-93 w/ 2jsf.
3. Acidize parts 10763-93 w/ 1000 gal 15% HCl
4. Swab test parts 10763-93
5. Put on gas lift.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>L. M. Williams</u>	TITLE <u>Prod. Engr</u>	DATE <u>7-13-70</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>SUPERVISOR DISTRICT</u>	DATE <u>15 19/0</u>
CONDITIONS OF APPROVAL, IF ANY:		