Submit 3 Copies to Appropriate

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240	D. Box 1980, Hobbs NM 88240		WELL API NO.		
DISTRICT II P.O. Drawer DD, Artesia, NM 88210			3D-D25-Q2705 5. Indicate Type of Lease		
DISTRICT III			5. Indicate Type of East	STATEX	FEE
1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lean E-9]		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A					
DIFFERENT RESER	POSALS TO DRILL OR TO DI VOIR. USE "APPLICATION F 101) FOR SUCH PROPOSALS	OR PERMIT"	7. Lease Name or Unit	Agreement Name	
1. Type of Well:	TO TO TO CONTENE TO COALS	9.7	STAT	E C	
OIL X GAS WELL	OTHER				
 Name of Operator Charles B. Gillespie, 	Tie		8. Well No.		
3. Address of Operator			9. Pool name or Wildca		
P.O. Box 8 Midland, Texas 79702			Townsend Permo Upper Penn		
4. Well Location Unit Letter Q . 2340) Cou+l	h 0.14			
Unit Letter $\frac{Q}{}$: $\frac{2340}{}$	Feet From The South	h Line and 910	Feet From The	East	Line
Section 1	Township 16-S	Range 35-E	NMPM Lea		County
	10. Elevation (Show v	whether DF, RKB, RT, GR, etc.)			
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data					
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK	PLUG AND ABANDON				
TEMPORARILY ARABBON				ERING CASING	
COMMENCE DRILLING OPNS.				G AND ABANDO	NMENT _
PULL OR ALTER CASING CASING TEST AND C			EMENT JOB		
OTHER:		OTHER:			[
12. Describe Proposed or Completed Operation work) SEE RULE 1103.	ONS (Clearty state all pertinent de	etails, and give pertinent dates, incl	uding estimated date of start	ing any proposed	
l. Set Cibp above pe	rforations at 10 F	5001 Press 4 GW GW			
2 Set 1001 plant to 5 (0)					
Flag at 5 5/5 casing side at 469/. Tag.					
3. Set 100' plug at 5-½" liner top at 4520'. Tag.					
	8" casing at 700'.				
5. Set 100' plug at 8-5/8" casing stub. 50' in and 50' out. Tag.					
6. Set 100' plug at 13-3/8" casing shoe at 336'. Tag.					
7. Set 15 SX plug at	surface.				
8. Weld 4" casing ma	rker to surface ca	asing. Clean locati	on.		•
100 PC46 Q	7500	•			
I hereby certify that the information above is true	·· · · · · · · · · · · · · · · · · · ·	edge and belief.		<u> </u>	
SIGNATURE Sum Will	lm	Production	Manager	8/11/93	
TYPE OR PRINT NAME Kevin Wid	ner		_	ELEPHONE NO683	
(This space for State Use) ORIGINAL S	IGNED BY IEEDY SEVEN				

- TITLE —

CONDITIONS OF AFFROVAL, IF ANY:

GNED BY JERRY SEXTON

DISTRICT I SUPERVISOR APPROVED BY-