

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.

3D-025-02706

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

E-9117

7. Lease Name or Unit Agreement Name

STATE C

8. Well No.

3

9. Pool name or Wildcat

Townsend Permo Upper Penn

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL  
WELL ☒

GAS  
WELL ☐

OTHER

2. Name of Operator

Charles B. Gillespie, Jr.

3. Address of Operator

P.O. Box 8 Midland, Texas 79702

4. Well Location

Unit Letter W : 992.5 Feet From The South Line and 2130.6 Feet From The East Line

Section

1

Township

16-S

Range

35-E

NMPM

Lea

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3968.8 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set Cbip above perfs at 10,550'. Dump 4 SX CMT on top of plug.

2. Set 100' plug at 8-5/8" casing shoe at 4721'. Tag.

3. Set 100' plug at 5-1/2" liner top at 4537'. Tag.

4. Cut and pull 8-5/8" casing at 700'.

5. Set 100' plug at 8-5/8" stub. 50' in and 50' out. Tag.

6. Set 100' plug at 13-3/8" casing shoe.

7. Set 15 SX plug at surface.

8. Weld 4" marker to surface casing. Clean location.

100' PLUG @ 7500

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Kevin Widner

TITLE

Production Manager

DATE 8/11/93

TYPE OR PRINT NAME

Kevin Widner

TELEPHONE NO. 683-1765

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

AUG 13 1993