

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION, C. C.

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

JUL 22 9 21 AM '69

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.
3-025-02169

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Humble Oil & Refining Co.	8. Farm or Lease Name Hulda A. Townsend
3. Address of Operator % Hobbs Pipe & Supply Co. Box 2010 Hobbs, N. M.	9. Well No. 10
4. Location of Well UNIT LETTER <u>E</u> <u>2130</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>9</u> TOWNSHIP <u>16-S</u> RANGE <u>35-E</u> NMFM.	10. Field and Pool, or Wildcat Townsend Wolfcamp
15. Elevation (Show whether DF, RT, GR, etc.) Unknown	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Spotted a 25-sx. plug to cover perf 10,409-10,470
2. Load hole with mud-laden fluid
3. Shoot and recover 3140'
4. Spot a 25-sx. plug at stub of 5 1/2
5. Shot and recover 1000' - 8 5/8" casg.
6. Spot a 25-sx. plug at stub of 8 5/8"
7. Spot a 25-sx. plug 419'
8. Spot a 10-sx. surface plug and set marker

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Manager DATE July 11, 1969

APPROVED BY [Signature] TITLE [Signature] DATE July 11, 1969

CONDITIONS OF APPROVAL, IF ANY: