

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>DEPLETED</u>	7. Unit Agreement Name
2. Name of Operator PAN AMERICAN PETROLEUM CORPORATION	8. Farm or Lease Name <u>STATE "AG"</u>
3. Address of Operator BOX 68, HOBBS, N. M. 88240	9. Well No. <u>1</u>
4. Location of Well UNIT LETTER <u>B</u> <u>660</u> FEET FROM THE <u>NORTH</u> LINE AND <u>1980</u> FEET FROM THE <u>EAST</u> LINE, SECTION <u>10</u> TOWNSHIP <u>16-S</u> RANGE <u>35-E</u> NMPM.	10. Field and Pool, or Wildcat <u>TOUNSEND Wolfcamp</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>4017' R. D. B.</u>	12. County <u>Lea</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

*Permitant to verbal auth to P.A 3-16-70 Mr. L. Clements to
A.M. Rande. abandonment to be as follows:*

*Spot 35' cement (across perfs 10516 - 10610') from PBD-10622 - 10450'.
Pull 5 1/2" from free point at 1st TCMT @ 8700'. 255x in & out of stub.
Spot 25 5x 8088-7988 (T.A. 8038)
" " " - 6305-6205 (T. 6255) } may be omitted if not exposed.
" 50 " in & out of 9 7/8" CSA 4675.
Pull 9 7/8" from free point at 1650'. 255x in & out of stub.
Spot 255x. @ Top of Salt @ 1910, if exposed
" 50 5x. in & out of 13 7/8" CSA 359
" 10 5x. @ surface, erect P & A marker.
make final cleanup and restore ground to contour.
TD - 10649
PBD - 10622
13 7/8" CSA 359 - Circ
9 7/8" CSA 4675 (T.CMT 1650)
5 1/2" CSA 10642 (TCMT 8705)*

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED	AREA SUPERINTENDENT	DATE
<i>[Signature]</i>		MAR 18 1970
APPROVED BY	TITLE	DATE
<i>[Signature]</i>		
CONDITIONS OF APPROVAL, IF ANY:		
1-SSSP		
1-RRy		