

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Harold L. Runnels		8. Farm or Lease Name Lusk
3. Address of Operator P. O. Box 937, Lovington, New Mexico		9. Well No. 1
4. Location of Well UNIT LETTER <u>b</u> , FEET FROM THE _____ LINE AND _____ FEET FROM THE _____ LINE, SECTION <u>11</u> TOWNSHIP <u>16 S</u> RANGE <u>35</u> NMPM.		10. Field and Pool, or Wildcat Townsend
15. Elevation (Show whether DF, RT, GR, etc.) DF 3993		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged as follows:

Set 25 SX plug on perforations at 10,257 to 10,286.
Shot 52" casing off and pulled. Loaded hole with Bentonite mud and set 25 SX cement plug in and out base of 52" at 7200. Spotted 25 SX plug at 5500. Spotted 25 SX plug at 4500. Spotted 25 SX plug at 300. Set 15 SX plug in top of hole with 4" dry hole marker in top.

Cleaned location and abandoned.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>John W. Runyan</u>	TITLE <u>Agent</u>	DATE <u>3/5/65</u>
APPROVED BY <u>John W. Runyan</u>	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		