DISTRIBUTION					
	RICOTION				
SANTA FE					
FILE					
U.S.G.S.					
LAND OFFICE					
TRANSPORTER	011				
	GAS				
PROBATION OFFIC	E				
OPERATOR					

## NEW MEXICO OIL CONSERVATION COMMISSIONS OFFICE OCC

MISCELLANEOUS NOTICES APR 27 PM

strict Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

Notice of Intention	1	N		1		-	
TO CHANGE PLANS		Notice of Intention Temporarily Abandon	N WELL		TO DRILL	P INTENTION Deeper	
NOTICE OF INTENTION TO PLUG WELL	-	NOTICE OF INTENTION TO PLUG BACK			Notice of to Set Li	Intention Ner	
Notice of Intention to Squeeze		Notice of Intention to Acidize		x	Notice of to Shoot	INTENTION (Nitro)	
Notice of Intention to Gun Perforate	x	Notice of Intention (Other)				INTENTION Dual Complet:	
OIL CONSERVATION COMMISSI	ION					Wolfcamp & D	evonian
SANTA FE, NEW MEXICO		Roswell	. New M	exico		April 2	5, 1962
Gentlemen:						(1-647)	
Following is a Notice of Intention							
Shell Oil Company (Company or C	Operator)		State	GĄ	Well No		<b>N</b>
SE	16	т. 155 в	36E	NAPA	Ca	udill_Devonia	(Unit)
							+Pool
Lea	Count	ty.					
	FULL	DETAILS OF PRO	POSED	DI AN OI	WORK		
(FO	LLOW I	NSTRUCTIONS IN T	HE RUL	ELAN UI	FGULATIO	NR \	
roposed Operation: Dual						113)	
. Pressure test casing	apone	evisting newfa	a ana w	olicamp	• # #		n 11 11
with flapper at 10,60	001.	evrooring beils	, purr	pump an	a tubing	, and set Mode	1 "D" packer
. Perforate 10,450'-10,	.464 (	(141). 10.4681-	10.4051	(271)	and 10 5	1) + 10 E2E+ /c	
. Run tubing, set plug	and pa	icker and treat	perfs.	10.450	-10.195	vith 500 mal 1	5% NEA and $30$
gal 10% retarded NEA.	•						
. Reset plug and packer	r and t	treat perfs 10,	514-10	,535' w	ith 500 (	gal 15% NEA an	d 3000 gal 15
recarded MEA.				1			
. Reset packer and swab	$\circ$ load.	·	-				
. Kill well with lease . Run 2 3/8" tubing to		and pull tubing	g, pack	er and	bridge p]	Lug.	
. Run 2 3/8" tubing to at 10,000, BOT type 2	2 bride	ve plug assembly	verer B	obe com	stinger	on bottom, Mo	del "J" packe:
into Model "D" packer	 C.	20 brag appetert	and M	ope com	pound cas	sing pump at 7	000' and stab
. Run 1" string to Mode	el "J",	set dual packe	er. and	stab 1	string	into Model ".	11
. Swab Permo-Penn and p	place c	n production.	-,		0		•
Approved April 26		19.62	<b>C1</b>		. a	-	
Except as follows:			Sl		L. Loopany	or Operator /	•••••••
					Company		
						R.a. La	ulin
			<b>By</b> .R.	A. Lo	<u>lery</u>	R.a. Jo	why
Approved			<b>By</b> .R.	A. Lo	ery	R. a. Jo	why
Approved DIL CONSERVATION COMMISSIO	ON		<b>By</b> .R.	A. Lo	ery	R.a. Jo	why .
Approved OIL CONSERVATION COMMISSIO	ON		ByR. Position.D	A. Lo Istrict Send C	Exploite	R. a. Jo	: