## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

וט פארושרווויו טויג וטוו	-1 -1(1	11416
w#. #F COFICE RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.\$.G.\$.		
LAND OFFICE		
OPERATOR		

## L CONSERVATION DIVISIO

DISTRIBUTION				Revised 10-1-78	
SANTA FE	SANT	SANTA FE, NEW MEXICO 87501			
FILE					Sa. Indicate Type of Lease
U.S.G.S.	_		•		State Fee X
LAND OFFICE					
OPERATOR	لـ				5. State Oil & Gas Lease No.
SUND	RY NOTICES AND RE	PORTS ON WE	ELLS		
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO CHILL ON TO DEFPLY ON PLUG BACK TO A DIFFERENT RESERVOIR.  USE "SAPPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)					
1.				<del></del> ,	7, Unit Agreement Name
WELL X WELL					
2. Name of Operator	OTHER.	<del>,</del>			8, Farm or Lease Name
St. Clair Energy Corporation				Caudill	
3. Address of Operator					9. Well No.
P.O. Box 1392 Midland, Texas 79702			1		
4. Location of Well				<del></del>	10. Field and Pool, or Wildcat
UNIT LETTER K	2310	South	2310	o o	Caudill Permo Penn
UNIT LETTER	PEET FROM THE		LINE AND	FEET FROM	OSUGITI LEI WO LEWI
<b>T</b> T <b>.</b>	2.7	15-9	261	n e	
THE WEST LINE, SECT	21 TIONTOWN	SHIP	RANGE	<u></u> нмрм,	
	15. Elevation	(Show whether DF	, RT, GR, etc.)	*	12. County
	111111				Lea ()()()()
16. Charle	Appending Ray Ta	I. Jinaan Nasa	CNi T	0.1	D
	Appropriate Box To	indicate Nati		•	
NCTICE OF	INTENTION TO:		S	UBSEQUENT	REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND	ABANDON R	EMEDIAL WORK		ALTERING CASING
TEMPORARILY ABANDON		٠,	OMMENCE DRILLING OF	.ns.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE P	LANS C	ASING TEST AND CEME	NY JOA	
			OTHER		
отнея					
17 Describe Proposed of Completed (	Operations (Clearly state a)	l pertinent details	and sive pertinent	dates including	estimated date of starting any proposed
work) SEE RULE 1103.	speciations (event) state at	permitted detailed	, and give periodent	saire, merasing	cutinated date of starting any proposed
1. Set 75 Sx Cem	ont Plug in / 1/s	n Cea 9133	1_0001! & Tag	Plug.	
			///I a Iab	- 1 n P •	
2. Circulate hole with 10# Salt Gel Mud.					
3. Shoot off & Pull 7890' 4 1/2" Csg. Spot 25 Sx cement plug 7940-7810 & Tag Plug.					
4. Set 35 Sx. Cement Plug & 5900'.					
5. Set 45 Sx. Cement Plug 4645-4800' In & Out 8 5/8" Csg. & Tag Plug.					
6. Set 35 Sx. Cei	m <b>xe</b> nt Plug @ 2100	) <b>'</b> .			
7. Shoot off & P	ull 896' 8 5/8"	Csg.			
8. Set 35 Sx Cement Plug @ 1540' & Set 50 Sx Cement Plug 940-840' & Tag Plug.					
9. Set 70 Sx. Cement Plug In & Out 13 3/8" Csg. & Tag Plug @ 170'					
				er•	
PBCP Plugging	Operations 9-22	2-87 thru 9-	-3U <del>-</del> 87		
Working Pits	& Well Cellar hav	re been fill	ed & location	n levelled	•
					4.
16. I hereby certify that the informatio	n shove is true and comple	e to the best of my	knowledge and beli	ef.	
2	·		-		
19 91.	7/	h an	n+		10-30-87
SIGHED COTTO Vom	Huse	TITLE Age	;11		DATE

OH & GAS INSPECTOR

.... FEB 5 - 1988