NEW MEXICO OIL CONSERVATION COMMISSION SANTA FE, NEW MEXICO

MISCELLANEOUS N	Ю	T	CES
-----------------	---	---	-----

SANTA FE, NEW MEXICO

MISCELLANEOUS NOTICES

SUBMIT THIS NOTICE IN TRIPLICATE TO THE DISTRICT OFFICE, OIL CONSERVATION COMMISSION, BEFORE THE WORK SPECIFIED IS TO BEGIN. A COPY WILL BE RETURNED TO THE SENDER ON WHICH WILL BE GIVEN THE APPROVAL, WITH

	ICM	CATE NATURE OF NOTICE BY	CHECKIN	NG BELOW	
NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL		NOTICE OF INTENTION TO DRILL DEEPER	
MOTICE OF INTENTION TO PLUG WELL		NOTICE OF INTENTION TO PLUG BACK	x	NOTICE OF INTENTION TO SET LINER	
NOTICE OF INTENTION TO SQUEEZE		NOTICE OF PITENTION TO ACCUEZE	x	NOTICE OF INTENTION TO SMOOT (NITRO)	
NOTICE OF INTENTION TO GUN PERFORATE	ж	NOTICE OF INTERTION (OTHER)		NOTICE OF INTENTION (OTHER)	
OIL CONSERVATION COM		Wakka Nav	Mosei oo	M 20 - 21	260
SANTA FE, NEW MEXICO		Hobbs, New Mexico		May 10, 1960	
Gentlemen.		(-1.1.1)		(and	
		thention t o do Certain W			
Humble Oil & Refining	Company_	D. H. Crockett et	٧ل <u>۾</u>	VEL NO. 2 IN	
NW WNE W	Manago) De sec	CR OPERATOR) 21 T 15S 2 3633	MAR	MA, Caudill Devonian	(UNIT) P
(40-ACRE SUBDIVISION)	CLAN AND ALL AND IN COMMENSOR	er gerafe byene of the grant Tables and Tabl			
Lea		5115 PETE			
4. Jahren de Amerikan der	marringans sames de es	o Detai,			
n The Control of the		. DETAILS OF PROFOSED	PLAN (NE WORK	
	FUL				
. Pull rods and tub	FUL FOLLOY) ing and	. DETAILS OF PROFOSED VINSTRUCTIONS IN THE RUD set cast iron bridge pl	es and		mately
. Pull rods and tub sacks cement on to	FUL FOLLOV ing and : op of it	. DETAILS OF PROFOSED V INSTRUCTIONS IN THE RUL set cast iron bridge pl	es AND ug at 1	RIGULATIONS) 2,300° and dump approxim	•
. Pull rods and tub sacks cement on to . Perforate bend 11	FUL FOLION ing and: op of it 955-11970	. DETAILS OF PROFOSED VENSTRUCTIONS IN THE RUD set cast iron bridge plots if results unsatisfa	es AND ug at 1 ctory s	RIGULATIONS)	-
Pull rods and tub sacks cement on to Perforate bend 11 If results unsati	FUL (FOLIOV ing and s op of it 955=11970 sfactory	DETAILS OF PROFOSED VENETRUCTIONS IN THE RULE set cast iron bridge places if results unsatisfated plug off Bend with ce	es AND ug at 1 ctory s	RIGULATIONS) 2,300° and dump approxim	•
Pull rods and tubes sacks cement on to Perforate bend 11 If results unsation Perforate wolform If necessary, stip	FULL (FOLLOY ing and s op of it 955-11970 sfactory p 10597 mult te w	DETAILS OF PROFOSED VINSTRUCTIONS IN THE RULE set cast iron bridge ploy if results unsatisfate plug off Bend with certain 10612°.	es AND ug at 1 ctory s	RIGULATIONS) 2,300° and dump approximations are with 1000 gals.	-
Pull rods and tube sacks cement on to Perforate bend ll. If results unsation Perforate Wolfcam If necessary, stip If results unsation	FULL (FOLLOV) ing and sop of it 955-11970 sfactory p 10597 mulate wi	PETAILS OF PROFOSED VENETRUCTIONS IN THE RULE set cast iron bridge plots if results unsatisfated plug off Bend with certain 10612°, ith 1000 gallons acid. plug off peri. 10597	es AND ug at 1 ctory s	RIGULATIONS) 2,300° and dump approximations are with 1000 gals.	-
Pull rods and tubes sacks cement on to Perforate bend 11. If results unsationable Perforate Wolfcam If necessary, stiple Perforate Wolfcam Perforate Wolfcam	FULI (FOLIOV ing and s op of it 955-11970 sfactory p 10597 mulate w sfactory p 10361-	FATAILS OF PROFOSED VINSTRUCTIONS IN THE RULE set cast iron bridge ploy, if results unsatisfa, plug off Bend with ce = 10612°, ith 1000 gallons acid. plug off perf. 1059710371°.	es AND ug at 1 ctory sment.	RIGULATIONS) 2,300° and dump approximations and dump approximations and dump approximations and dump approximations are setting and dump approximations are setting as a set of the set of	-
Pull rods and tubes sacks cement on to Perforate bend 11. If results unsationable Perforate Wolfcam If necessary, stipperforate Wolfcam If necessary, stipperforate Wolfcam If necessary, stipperforate Stipperforat	FULI (FOLIOV ing and sop of it 955-11970 sfactory p 10597 mula te w sfactory p 10361-	. DETAILS OF PROFOSED VINSTRUCTIONS IN THE RULE set cast iron bridge plot, if results unsatisfate plug off Bend with cell in 1000 gallons acid. plug off perf. 1059710371.	es AND sug at 1 ctory sugernt. - 10612 and test	RIGULATIONS) 2,300° and dump approximations and dump approximations and dump approximations are set in the set of the set	, mud
Pull rods and tub. sacks cement on to Perforate bend 11 If results unsation Perforate Wolfcom If necessary, stip Perforate Wolfcom If results unsation Perforate Wolfcom If necessary, stip If results unsation	FJU (FOLIOV ing and s op of it 955-11970 sfactory p 10597 mula te w sfactory p 10361- mula te w sfactory	. DETAILS OF PROFOSED VINSTRUCTIONS IN THE RULE set cast iron bridge plots if results unsatisfated plug off Bend with certain 10612°. ith 1000 gallons acid. plug off perf. 10597 10371°. ith 1000 gallons acid as plug off perforations	es AND sug at 1 ctory sugernt. - 10612 and test	RIGULATIONS) 2,300° and dump approximations and dump approximations and dump approximations and dump approximations are setting and dump approximations are setting as a set of the set of	, mud
Pull rods and tubes sacks cement on to Perforate bend 11 If results unsationally Perforate Wolfcam If necessary, stimple Perforate Wolfcam If necessary, stimple If results unsationally plug at surface ((FOLION ing and sop of it 955-11970 sfactory p 10597 mulate w sfactory p 10361- mulate w sfactory sfactory	PETAILS OF PROFOSED VINSTRUCTIONS IN THE RULE set cast iron bridge places if results unsatisfated plug off Bend with certain 10612°. ith 1000 gallons acid. plug off perf. 10597 10371°. ith 1000 gallons acid at plug off perforations abardon well.	es AND sug at 1 ctory sugernt. - 10612 and test	RIGULATIONS) 2,300° and dump approximations and dump approximations and dump approximations are set in the set of the set	, mud
Pull rods and tubes sacks cement on to Perforate bend 11 If results unsationally Perforate Wolfcam If necessary, stimple Perforate Wolfcam If necessary, stimple If results unsationally plug at surface ((FOLION ing and sop of it 955-11970 sfactory p 10597 mulate w sfactory p 10361- mulate w sfactory sfactory	PETAILS OF PROFOSED VINSTRUCTIONS IN THE RULE set cast iron bridge places if results unsatisfated plug off Bend with certain 10612°. ith 1000 gallons acid. plug off perf. 10597 10371°. ith 1000 gallons acid at plug off perforations abardon well.	es AND sug at 1 ctory sugernt. - 10612 and test	RIGULATIONS) 2,300° and dump approximations and dump approximations and dump approximations are set in the set of the set	, mud
Pull rods and tubes sacks cement on to Perforate bend 11 If results unsationally Perforate Wolfcam If necessary, stimple Perforate Wolfcam If necessary, stimple If results unsationally plug at surface ((FOLION ing and sop of it 955-11970 sfactory p 10597 mulate w sfactory p 10361- mulate w sfactory sfactory	PETAILS OF PROFOSED VINSTRUCTIONS IN THE RULE set cast iron bridge places if results unsatisfated plug off Bend with certain 10612°. ith 1000 gallons acid. plug off perf. 10597 10371°. ith 1000 gallons acid at plug off perforations abardon well.	es AND sug at 1 ctory sugernt. - 10612 and test	RIGULATIONS) 2,300° and dump approximations and dump approximations and dump approximations are set in the set of the set	, mud
Pull rods and tubes sacks cement on to Perforate bend 11 If results unsationally Perforate Wolfcam If necessary, stimple Perforate Wolfcam If necessary, stimple If results unsationally plug at surface ((FOLION ing and sop of it 955-11970 sfactory p 10597 mulate w sfactory p 10361- mulate w sfactory sfactory	PETAILS OF PROFOSED VINSTRUCTIONS IN THE RULE set cast iron bridge places if results unsatisfated plug off Bend with certain 10612°. ith 1000 gallons acid. plug off perf. 10597 10371°. ith 1000 gallons acid at plug off perforations abardon well.	es AND sug at 1 ctory sugernt. - 10612 and test	RIGULATIONS) 2,300° and dump approximations and dump approximations and dump approximations are set in the set of the set	, mud
Pull rods and tubes sacks cement on to Perforate bend 11 If results unsationally Perforate Wolfcam If necessary, stipperforate Wolfcam If necessary, stipperforate Wolfcam If necessary, stipperforate unsationally If results unsationally If results unsationally If results unsationally sacks and the sacks are sa	(FOLION ing and sop of it 955-11970 sfactory p 10597 mulate w sfactory p 10361- mulate w sfactory sfactory	PETAILS OF PROFOSED VINSTRUCTIONS IN THE RULE set cast iron bridge places if results unsatisfated plug off Bend with certain 10612°. ith 1000 gallons acid. plug off perf. 10597 10371°. ith 1000 gallons acid at plug off perforations abardon well.	es AND grant land tory soment. 10612 nd test 10361	RIGULATIONS) 2,300° and dump approximations and dump approximations and dump approximations are set in the set of the set	, mud

meb

: 6

MAME

ADDRESS_

Humble Oil & Refining Company

Bcx 2347, Hobbs, Vew Mexico