State of New Mexico E ,y, Minerals and Natural Resources Departmen.

Form C-103 Revised 1-1-89

AUG 27 1993

_ DATE -

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

P.O. Drawer DD, Artesia, NM 88210

OIL CONSERVATION DIVISION

P.O. Box 2088 Santa Fe, New Mexico 87504-2088 WELL API NO.

30-025-03726

5. Indicate Type of Lease

P.O. Drawer DD, Ariesta, NM 88210	STATE FEE X
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name
1. Type of Well:	
OBL X GAS OTHER	Snyder F
2. Name of Operator Charles B. Cillognic Tr	8. Well No.
Charles B. Gillespie, Jr. 3. Address of Operator	9. Pool name or Wildcat
P.O. Box 8 Midland, TX 79702	Townsend Permo Upper Penn
4. Well Location Unit Letter _ C :660 Feet From TheNorth	
Section 5 Township 16-S Range 36-E NMPM Lea County	
Section 5 Township 16-S Range 30-E. 10. Elevation (Show whether DF, RKB, RT, GR, etc.)	Y/////////////////////////////////////
(/////////////////////////////////////	
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING	3 OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING CASING CASING TEST AND CEMENT JOB	
OTHER: OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed	
work) SEE RULE 1103.	
**Cast Iron Bridge Plug was set @ 10,515' and covered with 2 sx cement on 5/9/88.	
1) Set 100' plug @ 7500'.	
Suspect casing or liner top leaking. Isolate leak and get recommendation from State.	
3) Set 100' plug @ 8 5/8" shoe @ 4714'. Tag.	
4) Set 100' plug @ 5 1/2" liner top @ 4537'. Tag/may combine with 8 5/8" plug.)	
THE COMMISSION MUST BE NOTICING OF	
6) Set 15 sx plug @ surface. PLUGING OF PLUGING OF SECUTIONS FOR THE GROOM	
7) Weld 4" marker to surface casing. Clean location.	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE Sum / White Production Manager DATE 8/25/93	
TYPE OF PRINT NAME Kevin Widner TELEPHONE NO. 915-683-1	

TILE -

ORIGINAL SIGNED BY JERRY SEXTON

DISTRICT I SUPERVISOR

(This space for State Use)

APPROVED BY-