	or management of the control of the	•			
Submit 3 Copies To Appropriate District	Conics To Appropriate District State of New Mexico		Form C-103		
Orrice	Energy, Minerals and Natural Resources		Revised March 25, 1999		
District I 1625 N. French Dr., Hobbs, NM 87240	Energy, wither are and readural resources		WELL API NO.		
District II	OIL CONCEDIVATION DIVISION		30-025-03735		
811 South First, Artesia, NM 87210 District III	2040 South Pacheco		5. Indicate Type of Lease		
1000 Rio Brazos Rd., Aztec, NM 87410			STATE XX FEE		
<u>District IV</u> 2040 South Pacheco, Santa Fe, NM 87505	• •			E9335-S	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or STATE	Unit Agreement Name:	
1. Type of Well; Oil Well 🔯 Gas Well 🔲 Other					
2. Name of Operator			8. Well No.		
Pronghorn Management Corporation			9. Pool name or Wildcat		
3. Address of Operator P. O. Box 1772 Hobbs, NM 88241			Townsend Perm	as Upper Penn	
4. Well Location	10005, 111 00241				
	4200 SSouth		500	. West .	
Unit Letter L	feet from the South	line and	feet from	the West line	
Section 6	Township 16-S	Range 36-E	NMPM Lea	County	
Section	10. Elevation (Show whether	DR, RKB, RT, GR, e			
	·				
	ppropriate Box to Indicate 1	Nature of Notice,	Report or Other D	opt of	
NOTICE OF IN	TENTION TO:	1	SEQUENT REP	ORT OF: ALTERING CASING	
PERFORM REMEDIAL WORK	PLUG AND ABANDON [22]	REMEDIAL WOF	ΛΛ <u> </u>	ALILINING CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DR	RILLING OPNS.	PLUG AND ABANDONMENT	
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST A CEMENT JOB	ND		
OTHER:		OTHER:			
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion					
or recompilation.					
1. Set C.I.B.P. @ 10,100'. Cap with 35' cement. 2. Circulate hole with mud laden fluid. 3. Nipple up to 5½" casing. Stretch, cut and pull ± 7000' casing. 4. Spot cement plug 50' in and out of stub. WOC - Tag. 5. Spot 100' cement plug 4799'-4699'. (Int. csg. shoe) WOC - Tag. 6. Spot 100' cement plug 2074'-1974'. (Top of salt) WOC - Tag. 7. Spot 10 sx. surface plug. 8. Erect dry hole marker. Clean location.					
25 SK PWG OR 100 WHICHEVER IS GREATER					
F 421 to 321'-	TAG				
,					
I hereby certify that the information	above is true and complete to the	e best of my knowle	edge and belief.		
mmil.	TITL			DATE4/7/00	
SIGNATURE DIVIN	IIIL	E rarener			
Type or print name G. A. BA	BER		Telepl	hone No. 505-393-9176	
(This space for State use)	- 1 V V V V V V V V V V V V V V V V V V	SPANTD BY			
APPPROVED BY	10 J	r a spri <u>d</u> B Y Gebeure		DATE	
Conditions of approval, if any:					
Conditions of approval, if any: THE COMMISSION MU HOURS PRIOR TO THE PLUGGING OPERATION	HE BECIMMINA OF				

TO BE APPROVED.

(Ap)