	NEW LKICO C	OIL CONSER	RVATION COMM	ION JON		
	_	Santa Fe, 1	New Mexico		APR A	1 1947
		ELLANE	OUS NOTIC	CES	ILUS	
Submit this noti	co in third oftalth the Oil Co	inservation Cor	mmission on its mean	an amount haf	ore the Guira are	dirt is
advisable, or the ed, and work sho the Commission.	will be returned to the send rejection by the Commissio build not begin with approval	on or agent, of l is obtained. S	the plan submitted ee additional instru	The plan as in the	approved should Rules and Regi	be follow- ulations of
une commission.		te nature of n	otice by checking	below:		
NOTICE OF IN SHUT-OFF	TENTION TO TEST CASH	NG	NOTICE OF INT CHEMICALI	ENTION TO LY TREAT V		
NOTICE OF INT	FENTION TO CHANGE PL	ANS	NOTICE OF INT OTHERWISE	ENTION TO E ALTER CA		
NOTICE OF IN	TENTION TO REPAIR WE		NOTICE OF INT	ENTION TO	PLUG WELL	x
NOTICE OF INT	ENTION TO DEEPEN WE	LL				
	<u> </u>	lobbs, New	Mexico Place		4-18-4 Date	7
Santa Fe, New M Sentlemen:						
	tice of intention to do certa					
Company or	Petroleum Company Operator	Loving	ton	Well No	. <u>1</u> in 1	1/2 SB/
of Sec. 35	, T <u>16-B</u> , R	36-B	N. M. P. M.	Lovingt	on	Field
FO T.D. 5002†	LLOW INSTRUCTIONS IN	ILS OF PRO THE RULES at 4679.35		NS OF THE C		10-3/4
	FULL DETAI LLOW INSTRUCTIONS IN 5-1/2" Casing set casing set 288.92" Fill open hol plug from 4680' to and shoot upward a	ILS OF PRO THE RULES at 4679.35 • • with hea 4640'. S t 100' int	AND REGULATION . 7-5/8" Cas vy mud from 50 hoot 5-1/2" ca ervals until c	NS OF THE C ing set a 02 ¹ to 46 sing. sta	t 2043.04 [†] . 80. Run 10 st rting at app:	x cemen rox. 21
	FULL DETAI LLOW INSTRUCTIONS IN 5-1/2" Casing set casing set 288.92" Fill open hol plug from 4680' to and shoot upward a 5-1/2" casing fill Start shootin upward until casin in bottom of 10-3/	ILS OF PRO THE RULES at 4679.35 • • with hea • 4640'. S t 100' int hole with g 7-5/8" c g is free. 4" casing,	AND REGULATION . 7-5/8" Cas vy mud from 50 hoot 5-1/2" ca ervals until c heavy mud. asing at 500' After pullin mud to surfac	NS OF THE C ing set a 02 ¹ to 460 sing, star asing is and shoot g 7-5/8 ⁿ e and cap	t 2043.04 [†] . 60. Run 10 s rting at app free. After p at 100 [†] inter casing place	x cement rox. 210 pulling ervals cement
	FULL DETAI LLOW INSTRUCTIONS IN 5-1/2" Casing set casing set 288.92" Fill open hol plug from 4680' to and shoot upward a 5-1/2" casing fill Start shootin upward until casin in bottom of 10-3/ cement cap and sta	ILS OF PRO THE RULES at 4679.35 • • with hea • 4640'. S t 100' int hole with g 7-5/8" c g is free. 4" casing,	AND REGULATION . 7-5/8" Cas . 7-5/8" Cas . 7-5/8" Cas 	NS OF THE C ing set a 02 [†] to 460 sing, star asing is : and shoot g 7-5/8 [#] of e and cap	t 2043.04 [†] . 80. Run 10 st rting at app: free. After p at 100 [†] into casing place casing with laum Company Operator	x cemen rox. 210 pulling ervals cement 10'
T.D. 5002 *	FULL DETAI LLOW INSTRUCTIONS IN 5-1/2" Casing set casing set 288.92" Fill open hol plug from 4680' to and shoot upward a 5-1/2" casing fill Start shootin upward until casin in bottom of 10-3/ cement cap and sta	ILS OF PRO THE RULES at 4679.35 • • with hea 4640'. S t 100' int hole with og 7-5/8" c g is free. 4" casing, ndard stee	AND REGULATION . 7-5/8" Cas . 7-5/8" Cas . 7-5/8" Cas 	NS OF THE C ing set a 02 [†] to 460 sing, star asing is : and shoot g 7-5/8 [#] o e and cap	t 2043.04 [†] . 80. Run 10 st rting at app free. After p at 100 [†] into casing place casing with	x cemen rox. 210 pulling ervals cement 10'
T.D. 5002 *	FULL DETAI LLOW INSTRUCTIONS IN 5-1/2" Casing set casing set 288.92" Fill open hol plug from 4680' to and shoot upward a 5-1/2" casing fill Start shootin upward until casin in bottom of 10-3/ cement cap and sta APR 21 1947	ILS OF PRO THE RULES at 4679.35 • • with hea 4640'. S t 100' int hole with og 7-5/8" c g is free. 4" casing, ndard stee	AND REGULATION . 7-5/8" Cas . 7-5/8" Cas . 7-5/8" Cas 	NS OF THE C ing set a 02 [†] to 460 sing, star asing is and shoot g 7-5/8 ⁿ e and cap	t 2043.04 [†] . 80. Run 10 st rting at app: free. After p at 100 [†] into casing place casing with leum Company Operator	x cemen rox. 210 pulling ervals cement 10'
T.D. 5002 * Approved xcept as follows OIL CO sy Mali	FULL DETAI LLOW INSTRUCTIONS IN 5-1/2" Casing set casing set 288.92" Fill open hol plug from 4680' to and shoot upward a 5-1/2" casing fill Start shootin upward until casin in bottom of 10-3/ cement cap and sta	ILS OF PRO THE RULES at 4679.35 • • with hea 4640'. S t 100' int hole with og 7-5/8" c g is free. 4" casing, ndard stee	AND REGULATION . 7-5/8" Cas . 7-5/8" Cas . 7-5/8" Cas 	NS OF THE C ing set a 02 [†] to 460 sing, star asing is and shoot g 7-5/8 ⁿ e and cap	t 2043.04 [†] . 80. Run 10 st rting at app: free. After p at 100 [†] into casing place casing with leum Company Operator intendent regarding well for	x cemen rox. 210 pulling ervals cement 10'

•

••<u>;</u>···••; · · · · ·

an an an an Araba an Araba an Araba. Bhan an anna <mark>an Araba an Araba an Araba an Araba an Araba an Araba an Araba. An Araba an Araba an Araba an Arab</mark>

and a state of the second s

and the second second

allow for the constant of a second of a second of a second of the second