

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

## OIL CONSERVATION DIVISION

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO.

**30-025-05157**

Indicate Type of Lease

STATE ☐

FEE ☒

State Oil & Gas Lease No.

### SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

Lease Name or Unit Agreement Name

J. C. Maxwell

Type of Well:

OIL  
WELL ☒

GAS  
WELL ☐

OTHER

Name of Operator  
Mobil Oil Corporation

Well No.

1

Address of Operator  
P.O. Box 4358 Houston, Texas 77210-4358

Pool name or Wildcat  
Denton Devonian

Well Location

Unit Letter P : 660 Feet From The East Line and 660 Feet From The South Line

Section 27 Township 14S Range 37E NMPM Lea County

Elevation (Show whether DF, RKB, RT, GR, etc.)  
3818 GR

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

#### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: Re-enter well to reabandon ☒

#### SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ANBANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1.) Notify NMOCDD of Intent to re-enter and plug and abandon
- 2.) Remove dry hole marker, hot tap casing plate, install casing extension and well head flange
- 3.) MIRU hoist and P&A equipment, install BOP
- 4.) Drill out top plug and tag bottom plug @ 11,930
- 5.) Condition 10# mud & POOH w/ bit
- 6.) RIH to 8300 and spot 100' plug to 8200'
- 7.) PUH to 5150 and spot 100' plug to 5050'
- 8.) PUH to 4870 and spot plug from 4870 to 4657 (shoe & TOL) WOC/tag
- 9.) PUH to 2250 and spot 100' plug to 2150' (salt)
- 10.) PUH to 512 and spot 100' plug to 412' (shoe plug) WOC/tag
- 11.) Spot 50' surface plug
- 12.) RDMO, cut off well head, install dry hole marker, cut off anchors, clean location

10 3/4" 29# @ 462', 7 5/8" 24# @ 4820', 5 1/2" 17&20# @ 12,670'

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*Russ Light*

TITLE Agent

DATE 07-20-00

TYPE OR PRINT NAME Russ Light

TELEPHONE NO. (915) 523-5155

(This space for State Use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL IF ANY:

