STATE OF NEW MEXICO	
ENERGY AND MINERALS DEPARTMENT	
OIL CONSERVATION	DIVISION
DISTRIBUTION P. O. BOX 2088	Form C-103
SANTA FE SANTA FE, NEW MEXIC	Revised 10-1-78
FILE	5a. Indicate Type of Leuse
U.S.O.S.	State State
	5. State Oil & Gus Lease No.
OPERATOR	
SUNDRY NOTICES AND REPORTS ON WELLS (DO HOT USE THIS FORM FUR PROPOSALS TO DRILL ON TO DEPLIN OR PLUG BACK TO A DI USE "VAPPOICATION FOR PERMIT -" IFORM C-1011 FOR SUCH PROPOSAL	IPPERENT RESERVOIR. ANN ANN ANN ANN ANN ANN ANN ANN ANN AN
1.	7. Unit Agreement Name
2. Name of Operator	8. Farm or Lease Name
Dhilling Dotroloum Company	Denton
Phillips Petroleum Company	9. Well No.
Room 401, 4001 Penbrook Street, Odessa, Texas 79762	12
A Location of Well	10. Field and Pool, or Wildcat
F 1080 porth	662 Denton Devonian
UNIT LETTER E 1980 FEET FROM THE NOTTH LINE AN	10 002 FEET FROM DEILOIT DEVOITAIL
THE West LINE, SECTION 11 TOWNSHIP 15-S RAN	37_F ())))))))))))))))))))))))))))))))))))
THE LINE, SECTION TOWNSHIP TO D RAN	<u>geлл-с</u> нмрм. Д////////////////////////////////////
11111111111111111111111111111111111111	R, etc.) 12. County
()))))))))))))))))))))))))))))))))))))	Lea
Check Appropriate Box To Indicate Nature of	-
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL	
	E DRILLING OPHS. PLUG AND ABANDONMENT
PULL OR ALTER CABING CASING TI	
OTHER Squeeze Devonian perfs 12350 - 12588; X	
Perf and test lower Devonian	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and gi	ve pertinent dates, including estimated date of starting any proposed
work) SEE RULE 1103.	
1. MI DDU, BOP, Reverse Unit w/tools and 10,000 feet of 2 3/8", J-55, and 3000 feet of	
2 3/8", N-80, EUE tubing. 2. Pick up 4 3/4" bit, 3 1/2" D.C.'s and 2 3/8" tbg.	
 Pick up 4 3/4" bit, 3 1/2" D.C.'s and 2 3/8" tbg. Clean out cement 12,242' and CIBP at 12,250'. Reverse hole clean at 12,570'. COOH. 	
4. GIH w/RTTS to set at 12,250'. Squeeze Devonian perfs, $12,350 - 12,558' w/200 sxs$	
of 15.6#/gal C1 "H" mixed w/0.05 LWL. Displace cmt w/40 bbls of wtr. By hesitation	
method displace next 7 bbls in stages to acquire a 1000 PSI squeeze. Release RTTS,	
pick up and reverse tubing clean.	
5. Pull RTTS to 12,050'. WOC 3 hrs. Set RTTS at 12,050'. Squeeze perfs 12,080 - 12,170'	
w/300 sxs of 15.6#/gal Cl "H" mixed w/0.05% LWL.	Displace $w/40$ bble utr By
hesitation method, displace next 6 bbls in stages to acquire a 1000 PSI squeeze.	
Release RTTS and reverse tubing clean. COOH.	to acquire a 1000 rbi squeeze.
6. GIH w/4 3/4" bit and DC's. Clean out cmt across perfs 12,080 - 12,170' and test to	
1000 PSI. Resqueeze as necessary.	
7. Clean out cmt across perfs 12,350 - 12,558' to 12,570' and test to 1000 PSI. Resqueeze	
as necessary.	
8. Clean out f/12,570' to 12,720'. Reverse hole clean. Spot 10 bbls of 10% Acetic acid	
at 12,675'. Displace w/47 bbls of wtr. COOH.	
18. I have by certify that the information above is true and complete to the best of my knowl	(cont. on back)
to, inverse contrast the fine the anomation above is true and complete to the best of my knowl	euge milu Dellel.
XALLunIII	
sicures W. J. Mueller vince Senior En	gineering Specialist DATE September 5, 1980
	★★★★ 0 3000
Orig. Signed by	3FK 8 1480
APPROVED BY John Runyan VITE	DATE
CONDITIONS OF APPROV Deologist	
	· ·

- 9. Run cased hole neutron-GR-collar log f/12,720' to 4650' w/5" detail to 9200' and 2" to 4650'
- 10. Perf 5 1/2" csg w/4" O.D. Casing gun using D. P. DML Charges at 2 JSPF: 12,600' - 12,610' 12,645' - 12,655' (20' - 40 holes)
- 11. GIH w/Baker Lock Set Packer open ended w/seating nipple on 2 3/8" tubing to set at 12,575'.
- 12. Acidize perfs w/2000 gals 15% NEFE HCL followed by 4000 gals of 28% NEFE HCL w/1 RCP ball sealer every 2 bbls of 28% acid in last 3300 gals.
- 13. Swab well to test and evaluate.

BOP Series 900, 3000# WP, double w/one set pipe rams and one set blind rams.



