

NO. OF COPIES RECEIVED			
DISTRIBUTION			
OFFICE			

3-NMOCC
1-File
NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
 Supersedes Old
 C-102 and C-103
 Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil Gas Lease No.
7. Unit Agreement No.
8. Farm or Lease Name
9. STATE "p"
11. Field and Pool, or Wildcat <i>Drilling</i> RADDOCK
12. County

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
 USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

1. <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-
2. Name of Operator GETTY OIL COMPANY
3. Address of Operator P.O. BOX 249, HOBBS, NEW MEXICO
4. Location of Well UNIT LETTER M 330 FEET FROM THE SOUTH LINE AND 330 FEET FROM LINE WEST LINE, SECTION 32 TOWNSHIP 16-S RANGE 37-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box to Indicate Nature of Notice, Report or Other **LE** Data
 NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	XX	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER <input type="checkbox"/>		OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated start and stop dates for any proposed work) SEE RULE 1103.

1. Fill hole with 9.5# brine mixed with 25 sxs per 100 bbl. salt gell.
2. Set BP @ 6120' with 35' Cement on Top.
3. Freepoint; cut; and salvage 5-1/2" casing.
4. Spot 100' cement plug 50' in and 50' out of 5-1/2" casing after cut off. (Cut off should be at approximately 3,500').
5. Spot 100' cement plug; 50' in and 50' out of 8-1/2" casing shoe @ 2093').
6. Place 10 sxs. cement plug at surface.
7. Fill in cellar and set P/A Marker.
8. Clean up location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED C.L. Wade: TITLE AREA SUPERINTENDENT DATE April 21, 1975
 Origin Started by C. L. Wade TITLE AREA SUPERINTENDENT DATE April 21, 1975
 APPROVED BY _____ TITLE _____ DATE _____
 CONDITIONS OF APPROVAL, IF ANY: