NUMBER OF COP	IES RECEIVED	
D	STRIBUTION	
SANTA FF		
FILE		
U.S.G.S.		
LAND OF FICE	1 -	
TRANSPORTER	OIL	
	GA3	
PRORAT ON OFF	CE	
OPERATOR		

1.

NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

MISCELLANEOUS NOTICES

strict Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See addi-

Notice of Intention			ow	
TO CHANGE PLANS	Notice of Intention to Temporarily Abandon Well		Notice of Intention to Drill Deeper	
Notice of Intention to Plug Well	Notice of Intention to Plug Back		Notice of Intention to Set Liner	
Notice of Intention to Squeeze	Notice of Intention to Acidize	х	Notice of Intention to Shoot (Nitro)	
Notice of Intention to Gun Perforate	Notice of Intention (Other)		Notice of Intention (Other)	
OIL CONSERVATION COMMISSION SANTA FE, NEW MEXICO	Roswell, No	ew Mexi	co April 1	, 1963
Gentlemen:				
	do certain work as described below at			
Shell Oil Contempor of Operation NE /4 NW /4 of Sec. 1	mpany Pries	st	Well No3in	C
NE NW 1/15 1	tor) Lease	X 73 470 4	Dan an Dawan	(Unit)
(40-acre Subdivision)	, 1, K3,E	,NMPM.		ıan
Lea	County.			
FI	LL DETAILS OF PROPOSED	DIANO	r work	
	W INSTRUCTIONS IN THE RUL			
POSED OPERATION:			,	
Pull rods, pump and tubing				
- Kin Worth Well Celimen di	rvev of open noie.	_	on at 12 502! and ton	
		OM NOO!	ser as re, je and cop	neakon
Run tubing w/two Lynes st		com pac		packer
Run tubing w/two Lynes strat 12,545'.	raddle packers. Set bott	_	-	
Run tubing w/two Lynes strat 12,545'.	raddle packers. Set bott gallons 15% FE/Acid; bet	_	-	
Run tubing w/two Lynes strat 12,545'. Treat below packer w/2000 acid; above packers w/3000 Pull tubing and packers.	raddle packers. Set both gallons 15% KK/Acid; bet Ogallons 15% FE acid.	ween p	-	
Run tubing w/two Lynes strat 12,545'. Treat below packer w/2000 acid; above packers w/3000 Pull tubing and packers.	raddle packers. Set both gallons 15% KK/Acid; bet Ogallons 15% FE acid.	ween p	-	_
Run tubing w/two Lynes strat 12,545'. Treat below packer w/2000 acid; above packers w/3000 Pull tubing and packers.	raddle packers. Set both gallons 15% KK/Acid; bet Ogallons 15% FE acid.	ween p	-	
Run tubing w/two Lynes strat 12,545'. Treat below packer w/2000 acid; above packers w/3000 Pull tubing and packers.	raddle packers. Set both gallons 15% KK/Acid; bet Ogallons 15% FE acid.	ween p	-	
Run tubing w/two Lynes strat 12,545'. Treat below packer w/2000 acid; above packers w/3000 Pull tubing and packers.	raddle packers. Set both gallons 15% KK/Acid; bet Ogallons 15% FE acid.	ween p	-	_
Run tubing w/two Lynes strat 12,545'. Treat below packer w/2000 acid; above packers w/3000 Pull tubing and packers.	raddle packers. Set both gallons 15% KK/Acid; bet Ogallons 15% FE acid.	ween p	-	_
Run tubing w/two Lynes strat 12,545'. Treat below packer w/2000 acid; above packers w/3000 Pull tubing and packers. Rerun tubing, rods, and packers.	raddle packers. Set both gallons 15% RE/Acid; bet Ogallons 15% FE acid.	ween po	ackers w/3000 gallons i	L5% FE
Run tubing w/two Lynes strat 12,545'. Treat below packer w/2000 acid; above packers w/3000 Pull tubing and packers. Rerun tubing, rods, and packers.	raddle packers. Set both gallons 15% RE/Acid; bet Ogallons 15% FE acid.	ween po	ackers w/3000 gallons i	L5% ITB
Run tubing w/two Lynes strat 12,545'. Treat below packer w/2000 acid; above packers w/3000 Pull tubing and packers. Rerun tubing, rods, and packers.	raddle packers. Set both gallons 15% EE/Acid; bet Ogallons 15% FE acid. ump and place on product:	ween po	Oil Company	L5% FE
Run tubing w/two Lynes strat 12,545'. Treat below packer w/2000 acid; above packers w/3000 Pull tubing and packers. Rerun tubing, rods, and packers.	gallons 15% FE Acid; bet Ogallons 15% FE acid. ump and place on product:	Shel	Oil Company Company or Operator ginal Signal Lowery R. A. LOV	ned By
Run tubing w/two Lynes strat 12,545'. Treat below packer w/2000 acid; above packers w/3000 Pull tubing and packers. Rerun tubing, rods, and packers as follows:	gallons 15% FE Acid; bet Ogallons 15% FE acid. ump and place on product:	Shell	Oil Company	ned By VERY
Run tubing w/two Lynes strat 12,545'. Treat below packer w/2000 acid; above packers w/3000 Pull tubing and packers. Rerun tubing, rods, and packers as follows:	gallons 15% FE Acid; bet Ogallons 15% FE acid. ump and place on product:	Shell	Oil Company Company or Operator in all Signal Signal Signal Lowery R. A. LOV	ned By VERY
at 12,545'. Treat below packer w/2000	gallons 15% FE Acid; bet Ogallons 15% FE acid. ump and place on product:	Shell Bis M	Oil Company Company or Operator in all Signal Signal Signal Lowery R. A. LOV	ned By VERY