

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>Amerada Petroleum Corporation</b>	8. Farm or Lease Name <b>W.W. Hamilton "A"</b>
3. Address of Operator <b>P.O. Box 668 - Hobbs, New Mexico</b>	9. Well No. <b>2</b>
4. Location of Well UNIT LETTER <b>I</b> , <b>660'</b> FEET FROM THE <b>East</b> LINE AND <b>1980</b> FEET FROM THE <b>South</b> LINE, SECTION <b>34</b> TOWNSHIP <b>16S</b> RANGE <b>38E</b> NMPM.	10. Field and Pool, or Wildcat <b>Knowles</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3709' DF</b>	12. County <b>Lea</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to pull rods, pump and tubing. Rerun 2-3/8" tubing with packer & holddown. Acidize open hole from 12,450' to 12,560' with 600 gals. Jel X-830 temporary plugging agent, 6000 gals. FLA X-2 acid and 4000 gals. reg. acid. Swab test. Pull tubing & packer. Run Kabe hydraulic pumping equipment and resume production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED D. C. Cappe TITLE District Superintendent DATE May 28, 1965

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: