n 25, 14. National State

...,

NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

Notice of Intention to Change Plans	Notice		1	1		1
		e of Intention to prarily Abandon Well		NOTICE OF INTE TO DRILL DEEPE		
Notice of Intention to Plug Well		of Intention o Back		Notice of Inter to Set Liner	NTION	
Notice of Intention to Squeeze	Nотісь то Асі	2 OF INTENTION DIZE	x	Notice of Inter to Shoot (Nite		
NOTICE OF INTENTION TO GUN PERFORATE	X Notice (Othe	of Intention r)		Notice of Inter (Other)	NTION	
OIL CONSERVATION COMMIS Santa Fe, New Mexico	SION	Roswell, New I	lexico	A	pril 17, 19	959
		(Place)			(Date)	
Gentlemen:						
Following is a Notice of Intent	tion to do certain w	vork as described below at	the			
		State E				
NE SW (Company o	or Operator)	Leese			ın	A
NE SW (40-acre Subdivision) ¼ of Sec.	, T	-16-S , R-35-E	,NMPM.	Townsen	d-Wolfcamp	P
Lea					•	
Pull rods, pump & tubi Perforate 10,505' - 10 Run tubing w/hookwall below packer.),530' w/2 je packer, w/po	et shots per foot rforations above	es and i		ll-plugged	
Perforate 10,505' - 10 Run tubing w/hookwall),530' w/2 je packer, w/po ,530' and 10, is above pack satisfactor	st shots per foot rforations above 545'.	packer	・ と tubing bul	ll-plugged	
Perforate 10,505' - 10 Run tubing w/hookwall below packer. Set packer between 10, Treat thru perforation Swab test. If results Run tubing, pump & rod),530' w/2 je packer, w/po ,530' and 10, is above pack satisfactor	st shots per foot rforations above 545'.	packer	・ と tubing bul	ll-plugged	
Perforate 10,505' - 10 Run tubing w/hookwall below packer. Set packer between 10, Treat thru perforation Swab test. If results Run tubing, pump & rod	D,530' W/2 je packer, W/po 530' and 10, as above pack satisfactor is.	et shots per foot rforations above 545'. ter w/3000 gallon ty, pull tubing.	packer s 15% a	• & tubing bu wcid.	V.	
Perforate 10,505' - 10 Run tubing w/hookwall below packer. Set packer between 10, Treat thru perforation Swab test. If results Run tubing, pump & rod Place on production.	D,530' W/2 je packer, W/po 530' and 10, as above pack satisfactor is.	et shots per foot rforations above ,545'. ter w/3000 gallon y, pull tubing.	packer s 15% a	• & tubing bul wcid. 11 Oil Compan Company or Oper	V	d By
Perforate 10,505' - 10 Run tubing w/hookwall below packer. Set packer between 10, Treat thru perforation Swab test. If results Run tubing, pump & rod Place on production.	D,530' W/2 je packer, W/po 530' and 10, is above pack satisfactor is.	et shots per foot rforations above 545'. ter w/3000 gallon y, pull tubing.	packer s 15% a She C. Caba	• & tubing bu wcid.	V Öffginal Signo Rex C. Caba	d By
Perforate 10,505' - 10 Run tubing w/hookwall below packer. Set packer between 10, Treat thru perforation Swab test. If results Run tubing, pump & rod Place on production.	D,530' W/2 je packer, W/po 530' and 10, is above pack satisfactor is.	et shots per foot rforations above 545'. ter w/3000 gallon Ty, pull tubing. , 19 ByRex. Position.	s 15% a s 15% a She C. Caba strict Send (• & tubing bul wcid. 11 Oil Compan Company or Oper aniss Exploitation	V Öffginal Signo Rex C. Caba	d By