Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, M. rals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT J P.O. Box 1980, Hobba, NM 88240 OIL CONSERVATION DIVISION P.O. Box 2088

DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088

WELL API NO.
30-055-21291

5. Indicate Type of Lease

STATE THE STATE

| SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM)—(101) FOR SUCH PROPOSALS.  Type of Well:  |  |               |                   |   |
|--|--|---------------|-------------------|---|
| (DO NOT USE THIS FORM FOR PROPASALS TO DISCIPLATION FOR PERMIT  (FORM C-101) FOR SUCH PROPOSALS  Type of Well:  Well   | DISTRICT III<br>000 Rio Brazos Rd., Aziec, NM 87410  |               |                   |   |
| Name of Operator  Address of Operator  PO Box 70, Lovington, NM 88260  Nest Kemnitz (W.C.)  West Kemnitz (W.C.)  West Kemnitz (W.C.)  West Kemnitz (W.C.)  West Kemnitz (W.C.)  North Lossidos  Use of North Lea Company  10. Elevation (Show whether DF. RRB, RT, GR, etc.)  4235 GT.  Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  REMEDIAL WORK PLUG AND ABANDON X  CHANGE PLANS CHANGE OPERATOR PLUG AND ABANDON X  PEMPORARILY ABANDON CHANGE PLANS CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONME  PULL OR ALTER CASING CHANGE PLANS CHANGE PROCESSER VULE 1103.  1. Set CIBP @ 10380' w/35' cmt on top.  2. TIH w/tbg. Load hole w/10# brine w/25# ge1/bb1.  3. Spot 20 sx cmt plug @ 7900'.  4. Shoot & pull casing 4480'  5. Spot 40 sx plug 4380-4480'  6. Shoot & pull 85/8' casing 1200'  7. Spot 40 sx plug at 80-4480'  6. Shoot & pull at surface  10. Install dry hole marker  The Partner DATE 15 marked to the bost of my knowledge and belief.  The Partner DATE 15 marked to 15 marked t | ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OH TO DEE  | PERMIT        | LUG BACK TO A     | 7. Lease Name or Unit Agreement Name          |
| Notice of Commence | . Type of Well:  |               |                   | 1   |
| Address of Operator P O Box 70, Lovington, NM 88260  West Kemnitz (W.C.)  West | . Name of Operator   |               |                   | 1   |
| P O Box 70, Lovington, NM 88260  West Letter I : 1980 Peat From The South  |  |               |                   |   |
| Well Lession   Usit Letter   1   1980   Peat From The South   Line and 600   Peat From The East  | , Address of Operator  D. O. Roy. 70 Lovington, NM 88260   |               |                   | West Kemnitz (W.C.)                           |
| TOWNSHIP 103.  TOWNSHIP 103.  TOWNSHIP 104. Elevation (Show whether Dr. RKB, RT, GR, etc.)  4235 Gr.  Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  REMEDIAL WORK ALTERING CASING  COMMENCE DRILLING OPNS. PLUG AND ABANDON CASING TEST AND CEMENT JOB  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of sterring any proposed work) SEE RULE 1103.  Set CIBP (10380' w/35' cmt on top.  THE W/tbg. Load hole w/10# brine w/25# gel/bbl.  Spot 20 sx cmt plug (7900'.  Shoot & pull casing 4480'  Shoot & pull 85/8' casing 1200'  Spot 40 sx plug 4380-4480'  Shoot & pull 85/8' casing 1200'  Spot 40 sx plug 345-445'  10 Install dry hole marker  Iherby certify that the factomasiposatory is true and complete to the bost of my knowledge and boiled.  THE PARTNER NO. 3966  THE PICKEN NO. 3966  THE | Uall Letter I : 1980, Feet From The South  |               | _                 | - County                                      |
| Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. LUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENCE DRILLING OPNS. OTHER:  12 Describe Proposed or Completed Operations (Clearly state all pertinent datails, and give pertinent datas, including astimated data of starting any proposed work) SEE RULE 1103.  1. Set CIBP @ 10380' w/35' cmt on top. 2. TIH w/tbg. Load hole w/10# brine w/25# ge1/bb1. 3. Spot 20 sx cmt plug @ 7900'. 4. Shoot & pull casing 4480' 5. Spot 40 sx plug & 4380-4480' 6. Shoot & pull 8 5/8' casing 1200' 7. Spot 40 sx plug in & out 1200' 8. 40 sx plug 345-445' 9. 10 sx plug at surface 10. Install dry hole marker  The Partner DATE 6-10-93 THE PRINCE NO. 3966  | Section 31 Township 16S  | Range         | XB. RT. GR. etc.) | MMM Lea V//////////////////////////////////// |
| Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING  TEMPORARILY ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB OTHER:  12 Describe Proposed or Completed Operations (Clearly state all pertinent datas), and give pertinent datas, including astimated data of starting any proposed work) SEE RULE 1103.  1. Set CIBP @ 10380' w/35' cmt on top. 2. TIH w/tbg. Load hole w/10# brine w/25# gel/bbl. 3. Spot 20 sx cmt plug @ 7900'. 4. Shoot & pull casing 4480' 5. Spot 40 sx plug 4380-4480' 6. Shoot & pull 8 5/8' casing 1200' 7. Spot 40 sx plug 345-445' 9. 10 sx plug at surface 10. Install dry hole marker  Thereby certify that the Micrometical aborts is true and complete to the best of my knowledge and balled.  THILE PARTNER  THILE PARTNER  DATE 6-10-93  THE PERFORM OF THE TOTHER TO THE TOTHER TO THE TEST TO THE TEST TOTHER TOTH | 7/////////////////////////////////////   | 5 Gr.         |                   |   |
| NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK  PLUG AND ABANDON  CHANGE PLANS  COMMENCE DRILLING OPNS. PLUG AND ABANDONME CASING  COMMENCE DRILLING OPNS. PLUG AND ABANDONME CASING TEST AND CEMENT JOB  OTHER:    12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including assimated date of starring any proposed work) SEE RULE 1103.  1. Set CIBP @ 10380' w/35' cmt on top. 2. TIH w/tbg. Load hole w/10# brine w/25# gel/bbl. 3. Spot 20 sx cmt plug @ 7900'. 4. Shoot & pull casing 4480' 5. Spot 40 sx plug 4380-4480' 6. Shoot & pull 8 5/8' casing 1200' 7. Spot 40 sx plug in & out 1200' 8. 40 sx plug 345-445' 9. 10 sx plug at surface 10. Install dry. hole marker    Iherby certify that the Thermatical beat of my knowledge and belief.   Partner   | Cl. A Appropriate Pox to Indic   | ate Nati      | re of Notice, R   | teport, or Other Data                         |
| PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONME  PULL OR ALTER CASING OTHER:    OTHER: O | 11. Check Appropriate box to male  | 1             | SUE               | SEQUENT REPORT OF:                            |
| TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONME  PULL OR ALTER CASING OTHER:  Thereby certify that the discomarion, there is true and complete to the best of my knowledge and belief.  Thereby certify that the discomarion, there is true and complete to the best of my knowledge and belief.  THE PART THE PLUG AND ABANDONME  COMMENCE DRILLING OPNS. PLUG AND ABANDONME  CASING TEST AND CEMENT JOB OTHER:   | C  | X R           |                   | [^  |
| CASING TEST AND CEMENT JOB  OTHER:  12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including astimated date of starting any proposed work) SEE RULE 1103.  1. Set CIBP @ 10380' w/35' cmt on top. 2. TIH w/tbg. Load hole w/10# brine w/25# gel/bbl. 3. Spot 20 sx cmt plug @ 7900'. 4. Shoot & pull casing 4480' 5. Spot 40 sx plug 4380-4480' 6. Shoot & pull 8 5/8' casing 1200' 7. Spot 40 sx plug in & out 1200' 8. 40 sx plug at surface 10. Install dry. hole marker  I hereby certify that the Mormation, above is true and complete to the best of my knowledge and belief.  SIGNATURE  TILE Partner  DATE 6-10-93  TELEPHONE NO. 396   | EHLOUM USWISSING ILOUR III   |               | SMALENCE DOUG IN  | GOPNS PLUG AND ABANDONMENT                    |
| OTHER:  12 Describe Proposed or Completed Operations (Clearly state all pertinent datails, and give pertinent datas, including estimated data of starting any proposed work) SEE RULE 1103.  1. Set CIBP @ 10380' w/35' cmt on top. 2. TIH w/tbg. Load hole w/10# brine w/25# gel/bbl. 3. Spot 20 sx cmt plug @ 7900'. 4. Shoot & pull casing 4480' 5. Spot 40 sx plug 4380-4480' 6. Shoot & pull 8 5/8' casing 1200' 7. Spot 40 sx plug in & out 1200' 8. 40 sx plug 345-445' 9. 10 sx plug at surface 10. Install dry hole marker  Thereby certify that the formula journal post is true and complete to the bost of my knowledge and belief.  Signature  Partner  Date 6-10-93 TELEPIENE NO. 396  | TEMPORARILY ABANDON CHANGE PLANS   | -1            |                   |   |
| 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  1. Set CIBP @ 10380' w/35' cmt on top. 2. TIH w/tbg. Load hole w/10# brine w/25# gel/bbl. 3. Spot 20 sx cmt plug @ 7900'. 4. Shoot & pull casing 4480' 5. Spot 40 sx plug 4380-4480' 6. Shoot & pull 8 5/8' casing 1200' 7. Spot 40 sx plug in & out 1200' 8. 40 sx plug 345-445' 9. 10 sx plug at surface 10. Install dry. hole marker  Thereby certify that the Mormatica, above is true and complete to the best of my knowledge and belief.  Signature Partner DATE 6-10-93   | PULL OR ALTER CASING   | $\neg$        |                   | EMENT JOB L                                   |
| 1. Set CIBP @ 10380' w/35' cmt on top. 2. TIH w/tbg. Load hole w/10# brine w/25# gel/bbl. 3. Spot 20 sx cmt plug @ 7900'. 4. Shoot & pull casing 4480' 5. Spot 40 sx plug 4380-4480' 6. Shoot & pull 8 5/8' casing 1200' 7. Spot 40 sx plug in & out 1200' 8. 40 sx plug 345-445' 9. 10 sx plug at surface 10. Install dry hole marker  Thereby certify that the information above is true and complete to the best of my knowledge and belief.  Signature  The Partner  Date 6-10-93  The Partner  Date 6-10-93   | OTHER:   | <u> </u>      |                   |   |
| 2. TIH w/tbg. Load hole w/10% brine w/23% gelf bol.  3. Spot 20 sx cmt plug @ 7900'.  4. Shoot & pull casing 4480'  5. Spot 40 sx plug 4380-4480'  6. Shoot & pull 8 5/8' casing 1200'  7. Spot 40 sx plug in & out 1200'  8. 40 sx plug 345-445'  9. 10 sx plug at surface  10. Install dry hole marker  The Partner  DATE 6-10-93  SKONATURE  THE Partner  DATE 6-10-93  | work) SEE RULE 1103.   |               |                   | uding estimated date of starting any proposed |
| 6. Shoot & pull 8 5/8' casing 1200 7. Spot 40 sx plug in & out 1200' 8. 40 sx plug 345-445' 9. 10 sx plug at surface 10. Install dry hole marker  Thereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNATURE  THE Partner  DATE 6-10-93  | <ol> <li>TIH w/tbg. Load hole w/10# br</li> <li>Spot 20 sx cmt plug @ 7900'.</li> <li>Shoot &amp; pull casing 4480'</li> <li>Spot 40 sx plug 4380-4480'</li> </ol>   | ine w         | /25# ge1/b        | ы1.   |
| 7. Spot 40 sx plug in & out 1200 8. 40 sx plug 345-445' 9. 10 sx plug at surface 10. Install dry hole marker  Thereby certify that the information above is true and complete to the best of my knowledge and belief.  SIONATURE Partner DATE 6-10-93  | $c_{boot} = c_{boot} $ | 200'          |                   |   |
| 8. 40 sx plug 345-445  9. 10 sx plug at surface  10. Install dry hole marker  Thereby certify that the later marker is true and complete to the best of my knowledge and belief.  SIGNATURE Partner DATE 6-10-93   | 7 Spot 40 sx plug in & out 1200  | ) ·           |                   |   |
| 10. Install dry hole marker  Thereby certify that the lateromation above is true and complete to the best of my knowledge and belief.  SHONATURE Partner DATE 6-10-93  TELEPHONE NO. 396   | 8 40 sx plug 345-445   |               |                   |   |
| THE Partner DATE 6-10-93   | 9. 10 sx plug at surface   |               |                   |   |
| SIGNATURE PARTIE PARTIE DATE TELEPHONE NO. 396   | 10. Install dry, note market   |               |                   |   |
| SIGNATURE Partner DATE TELEPHONE NO. 396   | I hereby certify that the information above is true and complete to the best of my know  | ledge and bei | id.               | 6-10-93                                       |
| TELEPHONE M. 396   | // VII Box 1 1   |               | Partner           | DATE TATE                                     |
| J. H. Garner   |  |               |                   | ТЕLЕРНОМЕ NO. 396-532                         |
| TYPE UR FRUIT I NAME   | TYPE OR PRINT NAME J. H. Garner  |               |                   |   |

(This space for State Under IGNAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR

JUN 15 1993

CONDITIONS OF APPROVAL, IF ANY: