

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. OG-866
7. Lease Name or Unit Agreement Name N. E. Maljamar Unit
8. Well No. 1
9. Pool name or Wildcat West Kemnitz (W.C.)
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4235 Gr.

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER
2. Name of Operator Kaiser-Francis Oil Company
3. Address of Operator P. O. Box 21468, Tulsa, OK 74121-1468

4. Well Location Unit Letter <u>I</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>600 660</u> Feet From The <u>East</u> Line Section <u>31</u> Township <u>16S</u> Range <u>33E</u> NMPM Lea County
--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set CIBP @ 10380' w/35' cmt on top.
2. TIH w/tbg. Load hole w/10# brine w/25# gel/bbl.
3. Spot 20 sx cmt plug @ 7900'. 25 SX
4. Shoot & pull 4 1/2" casing (est. @ 5000').
5. Spot 40 sx cmt plug 50' in & 50' out of top of 4 1/2" casing. Tag.
6. Spot 40 sx cmt plug from 4380'-4480'.
7. Spot 40 sx cmt plug from 345'-445'.
8. Spot 25 sx cmt surface plug.
9. Weld on cap & install DH marker.

Estimated starting date is 5/15/90.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE C. Jan Valkenburg TITLE Technical Coordinator DATE 3/27/90  
TYPE OR PRINT NAME Charlotte Van Valkenburg 918-494-0000 TELEPHONE NO.

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

MAR 30 1990