

| | |
|------------------------|--|
| NO. OF COPIES RECEIVED | |
| DISTRIBUTION | |
| SANTA FE | |
| FILE | |
| U.S.G.S. | |
| LAND OFFICE | |
| OPERATOR | |

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.
K-2813

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

| | |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/> | 7. Unit Agreement Name |
| 2. Name of Operator Standard Oil Company of Texas - A Division of Chevron Oil Company | 8. Farm or Lease Name State 22 |
| 3. Address of Operator 3610 Avenue S - Snyder, Texas 79549 | 9. Well No. 1 |
| 4. Location of Well UNIT LETTER H , 1980 FEET FROM THE N LINE AND 660 FEET FROM THE E LINE, SECTION 22 TOWNSHIP 15S RANGE 32E NMPM. | 10. Field and Pool, or Wildcat Burner Wolfcamp |
| 15. Elevation (Show whether DF, RT, GR, etc.) GR 4169.8 | 12. County Lea |

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

To plug and abandon. Proposed procedure:

1. Spot cement plug in 5 1/2" casing 9760-9620 (perfs 9722-9905).
2. Cut and recover 5 1/2" casing at lowest free point (approx. 7900').
3. Spot cement plug 4450-4550 (Base 8-5/8" casing - 4500').
4. Cut and recover 8-5/8" casing at lowest free point (est. 3000').
5. Spot cement plugs 325'-425' (Base 13-3/8" csg - 381') and 10' cement plug in top 13-3/8" casing.
6. Cap 13-3/8" with steel plate and install well marker.
7. Clear and level location.

Work estimated to start approximately 11-1-67.

25 SKS. @ 5 1/2" STUB...
25 SKS. @ TOP CLORIETA.
25 SKS. @ 8 5/8" STUB.
25 SKS @ TOP 3214.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED B. Davidson TITLE Lead Drilling Engineer DATE 10-11-67

APPROVED BY John W. Runyan TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: