Form 9-331 (May 1963)	DEPARTN	JNITEF STATES IENT C THE IN EOLOGICAL SURV	ITERIOR	SUBMIT IN TRIPLICATF* (Other instructions on verse side)	5. LEASE DESIGNATION	au No. 42-R1424.		
(Do not use th	6. IF INDIAN, ALLOTTEE OR THIBE NAME							
1. OIL GAS WE'L X GAS	7. UNIT AGREEMENT NAME							
2. NAME OF OPERATOR	8. FARM OR LEASE NAME							
J.M. Huber	Stoltz Federal							
3. ADDRESS OF OPERAT	9. WELL NO.							
1900 Wilco Building, Midland, Texas 79701					1			
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface					10. FIELD AND FOOL, OR WILDCAT			
1980' FEL	Morton Wolfcamp 11. SEC., T., E., M., OR BLK. AND SUBVEY OR ABEA							
			_		Sec. 12-158	5-34E		
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)		R, etc.)	12. COUNTY OB PARISH 13. STATE				
Blanket 4057 GL			GL		Lea	N.M.		
16.	Check Ap	propriate Box To Ind	icate Natur	e of Notice, Report, or C	)ther Data			
	ENT REPORT OF:							
TEST WATER SHUT		PULL OR ALTER CASING		WATER SHUT-OFF	REPAIRING			
FRACTURE TREAT		IULTIPLE COMPLETE	-	FRACTURE TREATMENT	- ALTERING C			
SHOOT OR ACIDIZE		BANDON*	-	SHOOTING OR ACIDIZING	J ABANDONME	NT <sup>+</sup>		
REPAIR WELL		HANGE PLANS		(Other) Status of Well X (NOTE: Report results of multiple completion on Well				
(Other)			Completion or Recompletion Report and Log form.)					

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

The Stoltz Federal No. 1 has encountered several tubing leaks over the past several months. We have now repaired or replaced the tubing string. Additionally, we have changed out the pumping equipment from a hydraulic jet pumping operation to a rod-beam pumping operation to improve the economics of continued operations. The well is being produced, and the current test indicates the well to be producing at a rate of 170 BWPD and 5.5 BOPD. We do expect the oil production rate to improve with time, and ultimately attain a rate of 50 BOPD. The well has not been shut in but has been a continuous operation. It appears to be just a matter of time in recovering water lost in the Wolfcamp formation as a result of changing out the tubing and down hole pumping equipment. We fully expect the well to recover to an economical oil producing rate by the end of August, 1976, as we are presently experiencing a gradual daily oil production increase.

18. I hereby certify that the foregoing is true and correct SIGNED James R. Sutherland	TITLE District	Production	Mgr date _	8/16/76
(This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE		AUG	FOR RECORD
*Se	e Instructions on Revers	e Si <b>de</b>		OGICAL SURVEY NEW MEXICO

## RECEIVED

I IC & 11976 CL CONSERVATION COMM. HOBBS, N. M.