

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease  
 State  Fee   
 5. State Oil & Gas Lease No.  
 L-113 & K-680

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Sun Oil Company	8. Farm or Lease Name New Mexico "T" State
3. Address of Operator P. O. Box 1861 Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER <u>B</u> , <u>1980</u> FEET FROM THE <u>East</u> LINE AND <u>660</u> FEET FROM THE <u>North</u> LINE, SECTION <u>9</u> TOWNSHIP <u>15 S</u> RANGE <u>32 E</u> N.M.P.M.	10. Field and Pool, or Wildcat Tulk Wolfcamp
15. Elevation (Show whether DF, RT, GR, etc.) GR 4316	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
 NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Since this well has reached the economic limits of production, we propose to begin plugging operations on or about 3-1-71 as follows:

1. Pull rods and tubing.
2. Set bridge plug @ 9750; place 4 sks cement on top; fill hole w/mud.
3. Shoot 5 1/2" casing @ 7000'; spot 30 sk plug @ 7662; 30 sk plug @ 5635; 30 sk plug @ 4150.
4. Shoot 8 5/8" casing @ 1500'; spot 55 sk plug @ 2750; 55 sk plug @ 2558; 55 sk plug @ 1270; 55 sk plug @ 465; 10 sk plug @ surface.
5. Set permanent marker; clear location and level all pits.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Proration Clerk DATE Feb. 17, 1971

APPROVED BY [Signature] TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

**RECEIVED**

**FEB 10 1971**

**OIL CONSERVATION COMM.  
HOBBES, N. M.**